



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL GENERAL SHIFT REPORT

Date: 19/06/2026

Area: OHP

Equipment	Job
co-14a,14b,13a,rsc0-6a	motor and panel side ppm is done.
co-14a,14b,13a,rsc0-6a	motor and panel side ppm is done.
co-59, gallery ; co-28 brs ; 35a,33a gallery ; om-24 peripheral area	lighting is improved
co-59, gallery ; co-28 brs ; 35a,33a gallery ; om-24 peripheral area	lighting is improved
co-8,9,10,2a gallery,	lighting improvement job is under progress.
co-8,9,10,2a gallery,	lighting improvement job is under progress.
JH o-2 Hoist	Failed Hoist CT motor is sent to ERS
JH o-2 Hoist	Failed Hoist CT motor is sent to ERS