



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 22/05/2026

Shift: C

Incharge(s): Nagendra Midde

| Sl No | Area | Equipment                     | Problem                                             | Action                      | From                 | To                   | Remarks |
|-------|------|-------------------------------|-----------------------------------------------------|-----------------------------|----------------------|----------------------|---------|
| 1     | OHP  | CC 130                        | MECH BRS ACTING DUE TO BELT PIECE                   | CUT IT THEN OK              | 02:45:00             | 03:00:00             |         |
| 2     | OHP  | TBS ON CO 21 LBC              | ZSS PROBE DAMAGED                                   | REPLACED                    | 05:35:00             | 05:50:00             |         |
| 3     | CHP  | SCR 2 ON CC 33 SIGNAL         | ETHERNET CONNECTIONS TIGHTENED NEAR MODEM           | THEN OK                     | 22:50:00             | 23:30:00             |         |
| 4     | CHP  | SCR 5 ON CC 38 SIGNAL MISSING | MODEM FROM S3 ON CC 111 REPLACED                    | THEN OK                     | 23:00:00             | 00:30:00             |         |
| 5     | WT   | OT 3                          | D2 TRIPPING ON 7 SATURATION FAULT                   | RESET                       | 22:30:00             | 05:30:00             | 7 TIMES |
| 6     | WT   | CT 2                          | M2 BREAK LUG AND BRIDGE RECTIFIER PROBLEM REPLACED, | REPLACED                    | 23:00:00             | 01:00:00             |         |
| 7     | WT   | CP 4                          | BREAKER TRIPPED                                     | MADE IT ON                  | 22:45:00             | 22:55:00             |         |
| 8     | WT   | OP1                           | BREAKER TRIPPED                                     | MADE IT ON                  | 00:30:00<br>01:00:00 | 00:40:00<br>01:10:00 |         |
| 9     | WT   | OP1                           | CABLE PROBLEM AT COL 35                             | C TYPE POWER ISOLATED AT 48 | 03:00:00             | 03:30:00             |         |