



वी.एस.पी  
VSP

RASHTRIYA ISPAT NIGAM LIMITED  
VISAKHAPATNAM STEEL PLANT  
RAW MATERIAL HANDLING PLANT  
ELECTRICAL GENERAL SHIFT REPORT

Date: 02/06/2026

Area: OHP

| Equipment                                                                             | Job                                                                                                                    |
|---------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------|
| tbs-1 on co-22                                                                        | RBC pile focus lamp fixed, 250W lamp is fixed.                                                                         |
| co-29 pullchord                                                                       | cable damaged towards t/e side, 15meters new cable is laid and restored in circuit.                                    |
| JH-O-14 h/e, bpc-1,bpc-2,<br>DB-1,CO-27a,<br>30a,31a,33a,35a,37a,38b,65 H/E<br>hoists | hoists ppm is done.                                                                                                    |
| co-46 h/e welding machine supply                                                      | 63A Isolator damaged, replaced and restored welding machine supply.                                                    |
| co-36,37,47,48                                                                        | motor side ppm is done. co-37 zss cage found damaged, replaced.                                                        |
| co-10,13 ; crusher-2                                                                  | motor and panel side ppm is done.                                                                                      |
| brc-2 on co-30                                                                        | HT transformer oil drained out, metal putty is applied at leakage area, oil top up is done, later transformer charged. |