



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 31/08/2026

Shift: B

Incharge(s): Saurabh Kumar Yadav,P Venkat Kiran,P Venkat Kiran

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	BRC-2	shifted from CO-31 to CO-28	Trail run is taken	14:00:00	16:30:00	
2	OHP	BRC-4	Shifted from CO-8A to (CO-31) F Bed	trail run is taken.	16:30:00	19:00:00	
3	OHP	CO 25	OLR acted	reset	17:41:00	18:03:00	3 times
4	OHP	co 26	OLr acted	reset	16:10:00	16:15:00	
5	OHP	WOBR on CO 29	LT not working,drive tripped ,due to jamming	reset	18:34:00	18:44:00	
6	CHP	CC 111 SCR 4	B/C NOT running,stop PB acted	PB released	16:10:00	16:20:00	
7	CHP	CC 36 S1	LT not working,M1 tripped	made on	16:50:00	17:00:00	2 times
8	CHP	CC 54	olr acted	reset	17:20:00	17:30:00	2 times
9	CHP	CC 131	motor tripped	reset	18:50:00	18:55:00	
10	CHP	CC 201	olr acted	reset	15:10:00	15:20:00	
11	CHP	CC 28	olr acted	reset	15:20:00	15:30:00	
12	CHP	cc 29	zss acted,coal stucked in cage	cage removed	17:10:00	17:20:00	
13	CHP	CC 203	ZSS acted,probe wire not connected properly to module	connected properly	17:40:00	17:50:00	