RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL GENERAL SHIFT REPORT

Date: 15/10/2026

Area: OHP

Equipment	Job
cr-3a Gap adjustment	checked no problem is found, gap adjustment done, bubble memory valve is to be fixed in proper position.
tbs-1 on co-20	crmp side LT brake problem to be checked further.
rsco-10a to co-3a ; co-12 to co-3a hute vibrators	base bolts changed and fixed properly in place. trail run is taken.