



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL GENERAL SHIFT REPORT

Date: 10/07/2026

Area: OHP

Equipment	Job
co-38a,38b hoists	ppm is done.
co-38a,38b hoists	ppm is done.
OM-16,1-141LC3,1-141LC4 GROUND FLOOR, LC-7	RIO's PPM is done.
OM-16,1-141LC3,1-141LC4 GROUND FLOOR, LC-7	RIO's PPM is done.
JH O-3 ; JH O-2	LDB PPM is done, JH O-2 hoists ppm is done.
JH O-3 ; JH O-2	LDB PPM is done, JH O-2 hoists ppm is done.
vs-1 removed motor	shifted to lc-7, coupling removed. planned to be sent for overhauling. Spare motor identified and trail run is taken.
vs-1 removed motor	shifted to lc-7, coupling removed. planned to be sent for overhauling. Spare motor identified and trail run is taken.
LOSP-1 vf-19 level	100A mcb burnt, replaced and restored welding machine supply.
LOSP-1 vf-19 level	100A mcb burnt, replaced and restored welding machine supply.
co-24 brs	sensors canopy is provided.
co-24 brs	sensors canopy is provided.
space heaters of HT couplers	inspection done, found working.
space heaters of HT couplers	inspection done, found working.
Failed BRC transformer	oil removed and cleaning done, planned to be sent to ERS.
Failed BRC transformer	oil removed and cleaning done, planned to be sent to ERS.
brc-2 on repair bay	mcc cleaning, cable dressing done
brc-2 on repair bay	mcc cleaning, cable dressing done
tbs-1 on co-22, co-22	motor and panel side ppm is done.



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL GENERAL SHIFT REPORT

Date: 10/07/2026

Area: OHP

Equipment	Job
tbs-1 on co-22, co-22	motor and panel side ppm is done.