



वी.एस.पी  
VSP

# RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 20/09/2026

Shift: A

Incharge(s): Nagendra Midde

| Sl No | Area | Equipment            | Problem                                               | Action              | From     | To       | Remarks                  |
|-------|------|----------------------|-------------------------------------------------------|---------------------|----------|----------|--------------------------|
| 1     | OHP  | WOBR ON CO 6A        | LT NOT TAKING PLACE/M4 OLR ACTED                      | RESET DONE /3 TIMES | 09:30:00 | 09:40:00 |                          |
| 2     | OHP  | WOBR ON CO26         | LT NOT TAKING PLACE/DRIVE TRIPPED ON OLR              | RESET DONE          | 10:00:00 | 10:10:00 | WHEEL NOT ROTATING AT M2 |
| 3     | OHP  | SB 6 -CO 42A TAILEND | NOT WORKING/AIR LEAKAGE IN PIPE LINE AT CYLINDER      | INFORM TO OPE.      | 07:00:00 | 07:30:00 |                          |
| 4     | OHP  | CC 22                | ZSS ACTING/PROBE CABLE JJOINT OPEN                    | RE-JOINTED THEN OK  | 09:15:00 | 09:30:00 |                          |
| 5     | OHP  | TBS ON CO 22         | LT NOT TAKING PLACE/ BRAKE RESTENCES 2 NOS GOT MELTED | PENDING TO B SHIFT  | 13:00:00 | 14:00:00 | NO DELAY                 |
| 6     | OHP  | WOBR ON CO 26        | LT NOT TAKING PLACE/M4 TRIPPED ON OLR                 | RESET DONE          | 13:40:00 | 13:55:00 |                          |
| 7     | OHP  | CO 26                | TRIPPED ON OLR                                        | RESET DONE          | 12:15:00 | 12:25:00 |                          |
| 8     | OHP  | CO 25                | TRIPPED ON OLR                                        | RESET DONE          | 10:10:00 | 10:20:00 |                          |
| 9     | OHP  | CO 29                | TRIPPED ON OLR                                        | RESET DONE          | 09:45:00 | 09:50:00 |                          |
| 10    | CHP  | CC 22 C/D            | TRIPPED ON OLR                                        | RESET DONE          | 07:15:00 | 07:20:00 |                          |
| 11    | CHP  | SCR 4 ON CC 111      | NO DRIVES RUNNING/ SIGNAL MISSING                     | NEW MODEM REPLACED  | 07:00:00 | 07:15:00 |                          |



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 20/09/2026

Incharge(s): Nagendra Midde

Shift: A

| Sl No | Area | Equipment       | Problem                                                                          | Action                                                                                                  | From     | To       | Remarks |
|-------|------|-----------------|----------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------|----------|----------|---------|
| 12    | CHP  | S1 ON CC 36     | NO DRIVES RUNNING/FEEDER 2 TRIPPED AT 1-12 LBDS 4 and 5 AND HT FUSES 3 NOS BLOWN | CHECKED AT COUPLER AND I/O PANEL ,DIDNT FOUND ANY PROBLEM FUSES REPLACED AND HT POWER MADE ON TESTED OK | 10:05:00 | 11:00:00 |         |
| 13    | CHP  | SCR 8 ON CC 112 | SLEW NOT TAKING PLACE/CO.NO 33 CJB 1 TO CJB2                                     | SPARE REPLACED CORE NO.50 THEN OK                                                                       | 11:10:00 | 11:10:00 |         |
| 14    | WT   | SCO 1A          | ZSS ACTEDING/PROBE GAP DISTRUB                                                   | PROBE GAP ADJUSTED                                                                                      | 13:10:00 | 13:15:00 |         |