



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 10/08/2026

Incharge(s): M Srinivas

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	tbs-4 on co-21	LT not taking place	m2 thermal olr tripped, reset done.	12:20:00	12:30:00	
2	OHP	co-26	dmpr tripped on r-p once, olr once	disabled r-p , olr reset done	11:20:00 13:20:00	11:45:00 13:30:00	
3	CHP	SCR 2	BW not running	Drive tripped/Reset	08:05:00	08:15:00	
4	CHP	CC 31 SCR 1	LT tripped	M 6 tripped/Reset	10:55:00	11:10:00	
5	CHP	SCR 1	LT not moving	Drive tripped on OVA/Reset	13:15:00	13:25:00	
6	WT	OP-3 D-2	olr tripped	reset done	13:30:00	13:40:00	