



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL GENERAL SHIFT REPORT

Date: 14/07/2026

Area: OHP

Equipment	Job
brc-3 on co-34	shifted from co-34 to 33m. Panels blowing is done, 33m ht coupler is checked, found ok.
brc-3 on co-34	shifted from co-34 to 33m. Panels blowing is done, 33m ht coupler is checked, found ok.