



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 09/10/2026

Incharge(s): Nagendra Midde

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO 8 ZSs	Belt slipping	Informed to Oprn	08:05:00	08:20:00	
2	OHP	CO 20 BRS	Module Problem	Bypassed	11:00:00	11:30:00	TO be Replaced
3	OHP	CO 19 BRS	Fuse Blown	Replaced	12:30:00	12:50:00	
4	OHP	CBMS on CO 2a	MPCB is in Off condition	Made it on	08:15:00	08:30:00	
5	OHP	S3 on CC112 B/C	OLR acted	Reset	06:20:00	06:30:00	
6	CHP	CC 51	Panel Outgoing Finger Contacts Problem	Replaced	07:30:00	10:00:00	