RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL GENERAL SHIFT REPORT

Date: 01/11/2026

Area: OHP

Equipment	Job
brc-4 on co-8a	pcrd penudum switch contacts are not making , to be checked further, pcrd control mcb, pcrd mpcb to be replaced.
wbr-2 on co-29	LT M4 motor failed, disconnected, to be changed