



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 13/05/2026

Incharge(s): G Eswara Rao

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	co 16	tripped on olr /5 times	reset done	08:50:00	09:10:00	
2	OHP	CO 26	TRIPPED ON OLR	RESET DONE	09:40:00	09:50:00	
3	OHP	BRC ON CO 32	LT NOT TAKING PLACE	RESET DONE AT CABIN	10:40:00	10:50:00	
4	CHP	CC 33	110 KW NEW MOTOR REPLACED	CLEARANCE GIVEN AT 1130AM	06:30:00	11:30:00	MOTOR BURNT IN C SHIFT
5	CHP	CC 44	TRIPPED ON OLR/2 TIMES	RESET DONE	07:40:00	07:45:00	
6	CHP	CC 125	TRIPPED ON OLR	RESET DONE	08:00:00	08:05:00	
7	CHP	SCR 3 ON CC37	SLEW NOT TAKING PLACE/SLEW AREA JAMMING	INFORM TO OPERATION	10:50:00	11:00:00	
8	CHP	CC 51	MPD TRIPPED ON OLR	RESET DONE 2 TIMES	08:30:00 10:40:00	08:40:00 10:50:00	FEEDING C ONV.STOP PED
9	CHP	TIS ON CC 52	FEED BACK MISSING/TIS ZSS PROBE PLATE BEND GAP DISTRUB	GAPADJUSTED THEN OK	12:30:00	13:00:00	
10	CHP	CC 201	TRIPPED ON OLR	RESET DONE	13:35:00	13:40:00	
11	CHP	CC 203	TRIPPED ON OLR	RESET DONE	13:25:00	13:30:00	