



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 29/04/2026

Shift: A

Incharge(s): G Eswara Rao

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	co 26	tripped on olr	reset done	07:40:00	07:50:00	4 TIMES
2	OHP	WOBR ON CO 6A	LT NOT TAKING PLACE/M 5 GOT EARTH FAULT	TERMINATION DISCONNECT ED AT PANEL TB	07:00:00	07:30:00	PH.SEQ R,Y,B
3	OHP	WOBR ON CO 26	LUFFING NOT TAKING PLACE	WRONG COMPLAINT	06:40:00	07:00:00	
4	CHP	CC 51	TRIPPED ON OLR IN MPD	RESET DONE /2TIMES	10:35:00	11:00:00	
5	CHP	SCR 3 ON CC37	LT NOT TAKINGPLACE/DRIVE TRIPPED ON OLR	RESET DONE	07:15:00	07:25:00	
6	CHP	SCR 7 ON CC39	LT NOT TAKING PLACE/DRIVE TRIPPED ON OLR/ 2 TIMES	RESET DONE	10:30:00 12:00:00	10:40:00 12:10:00	
7	WT	OP 4	FORWARD /REVERSE NOT TAKIN PLACE/D2 OLR ACTED	RESET DONE	08:30:00	08:40:00	
8	WT	OT 3	DRIVE TRIPPED ON OLR	RESET DONE	09:30:00	09:40:00	