



वी.एस.पी  
VSP

# RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL GENERAL SHIFT REPORT

Date: 24/06/2026

Area: OHP

| Equipment                                              | Job                                                                                                                                       |
|--------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------|
| co-65,66,67 H/E ,T/E and gallery, 62,63 shuttle level, | Lighting is improved.                                                                                                                     |
| co-65,66,67 H/E ,T/E and gallery, 62,63 shuttle level, | Lighting is improved.                                                                                                                     |
| CR-1A,CR-2A                                            | Both motors greasing at both ends is done.                                                                                                |
| CR-1A,CR-2A                                            | Both motors greasing at both ends is done.                                                                                                |
| CR-3A motor Bearing End cover                          | End cover got damaged at NDE side, removed motor and shifted to CME,                                                                      |
| CR-3A motor Bearing End cover                          | End cover got damaged at NDE side, removed motor and shifted to CME,                                                                      |
| wobr-2 on co-29                                        | LT drive restored in VFD and checked LT operation,                                                                                        |
| wobr-2 on co-29                                        | LT drive restored in VFD and checked LT operation,                                                                                        |
| LC-8,LC-6,om-16,12,hvmcc-1                             | RIO bypass checked and list prepared.                                                                                                     |
| LC-8,LC-6,om-16,12,hvmcc-1                             | RIO bypass checked and list prepared.                                                                                                     |
| co-5a T/E, co-22 T/E , co-29 Yard focus lamps          | Lighting is rectified and restored.,                                                                                                      |
| co-5a T/E, co-22 T/E , co-29 Yard focus lamps          | Lighting is rectified and restored.,                                                                                                      |
| brc-5 on co-32                                         | MCC and CJB-1 Blowing is done.                                                                                                            |
| brc-5 on co-32                                         | MCC and CJB-1 Blowing is done.                                                                                                            |
| Wobr-3 on co-25                                        | PCRD limit checked, limit arm got free and was not stopping after acting, welded a piece to stop over traveling. and restored in circuit. |
| Wobr-3 on co-25                                        | PCRD limit checked, limit arm got free and was not stopping after acting, welded a piece to stop over traveling. and restored in circuit. |
| TT-3 AND CO-16 ;<br>co-15,tt-2,17,76R                  | motor and panel side PPM DONE                                                                                                             |



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL GENERAL SHIFT REPORT**

Date: 24/06/2026

Area: OHP

| Equipment                             | Job                                                                                                              |
|---------------------------------------|------------------------------------------------------------------------------------------------------------------|
| TT-3 AND CO-16 ;<br>co-15,tt-2,17,76R | motor and panel side PPM DONE                                                                                    |
| TT-3                                  | CABLE CHECKING DONE AND middle changeover area drum extra loop provided, and its behavior with TT LT is checked. |
| TT-3                                  | CABLE CHECKING DONE AND middle changeover area drum extra loop provided, and its behavior with TT LT is checked. |