



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 26/07/2026

Incharge(s): Saurabh Kumar Yadav

Shift: A

| Sl No | Area | Equipment   | Problem                               | Action                                                            | From     | To       | Remarks               |
|-------|------|-------------|---------------------------------------|-------------------------------------------------------------------|----------|----------|-----------------------|
| 1     | OHP  | co-12A      | zss acted                             | zss is acting due to belt overload, material removed and started. | 11:50:00 | 12:00:00 | no electrical problem |
| 2     | OHP  | BRC on CO8A | CT not working, drive tripped         | reset                                                             | 10:55:00 | 11:10:00 |                       |
| 3     | OHP  | CO 26       | olr acted                             | reset                                                             | 11:25:00 | 11:35:00 |                       |
| 4     | CHP  | cc 51       | mpd acted                             | reset                                                             | 12:25:00 | 12:30:00 |                       |
| 5     | IOSA | OC 11A      | healthy stop,                         | checked found all ok                                              | 07:20:00 | 07:35:00 |                       |
| 6     | IOSA | OC 4A       | PC acted due to material fall on rope | PC released                                                       | 07:20:00 | 07:40:00 |                       |