RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL GENERAL SHIFT REPORT

वी.एस.पी
VSP

Date: 14/11/2026

Area: OHP

Equipment	Job
CO 45	PULLCORD WORK UNDER PROSES
VS 1A,2A,3A	PANEL AND MOTOR SIDE PPM DONE
CR 3A	LUBRICATION PUMP MOTOR REPLACED WITH OLD ONE ,TESTED AND GIVEN CLEARENCE
SUMP PUMP	FLANGE PREPARATION DONE
CO 65,67	BRS INSPECTION DONE
CO 8A	CHUTE VIBRATOR BEARING PROBLEM ,SHIFTED TO LUCKY STORE
CO 8A	LED 120W LIGHT PROVIDED AT TAKEUP AREA
CO 31A	ONE 30 W LED LIGHT PROVIDED AT BRS AND CKT RECTIFICATION DONE
RCO 2A	SAFETY DEVICES ,PPM DONE
MCC ROOM	ONE TUBE LIGHT PROVIDED
CO 29	TIS INSPECTION DONE
WOBR 2 ON REPAIR BAY	T/F HTAND LT TERMINATION TIGHTNING DONE
WOBR 2 ON REPAIR BAY	LT BRAKE CABLE LAYING AND DRESSING DONE ,KEPT IN CKT
WOBR ON REPAIR BAY	LT BRAKE PANEL WELDING DONE
WOBR 2 ON REPAIR BAY	PLC PANEL WELDING DONE
WOBR 2 ON REPAIR BAY	PLC PANEL SHIFTED FROM HVMCC WOBR
TBS 1 ON CO 20	LT BRAKES MAGNETISING OK BUT MECHANICAL BRAKE ADJUSTMENT TO BE DONE. INFORM TO MECH.
BRC 2 ON CO 28	LT BRAKES CHECKING AND RECTIFICATION UNDER PROSES
CO 25,26,29	HOIST INSPECTION AND LOAD TESTING DONE
CO 25,26,20,29	MOTOR VIBRATION READING DONE
ASO OFFICE LIGHTING	18 NOS 35 W LIGHTS PROVIDED

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL GENERAL SHIFT REPORT

वी.एस.पी
VSP

Date: 14/11/2026

Area: OHP

Equipment	Job
CO 2A ,CO 10 LIGHTING	5 NOS LED LIGHTS PROVIDED AT3NOS TAILEND AND 2NOS GALLARY
CO 8,9 GALLORY LIGHTING	3 NOS 30 W LED LIGHTS PROVIDED AT TAILEND AND GALLORY
VF 4,5	FEED RATE INCREASED TO 90%