



वी.एस.पी  
VSP

RASHTRIYA ISPAT NIGAM LIMITED  
VISAKHAPATNAM STEEL PLANT  
RAW MATERIAL HANDLING PLANT  
ELECTRICAL GENERAL SHIFT REPORT

Date: 04/06/2026

Area: OHP

| Equipment                                | Job                                                                                          |
|------------------------------------------|----------------------------------------------------------------------------------------------|
| co-5,6,7,1a tunnel                       | lighting is improved.                                                                        |
| co-20 ht motor                           | vibration readings are taken.                                                                |
| wobr-1 on co-26                          | bucket wheel and boom conveyor inspection is done, vibration reading taken.                  |
| co-30,31                                 | mechanical brs installation is under progress,                                               |
| brc-2 operator cabin AC                  | MCB mechanism issue, cleaned and restored AC working.                                        |
| Spare motors                             | wobr-4 LT m5 spare motor and wob-1,2,3 BW spare motor received from ERS and kept at HVMCC-1. |
| Transformer 400VA                        | Received from ERS and kept at HVMCC-1.                                                       |
| co-11a brs                               | electronic brs kept bypass at module to belt holes and kept only mechanical brs in circuit.  |
| tbs-5 on co-24 and co-24                 | motor and panel side ppm is done. TBS LT brake panel base plate welding to be done.          |
| co-60,63 belt and carriage ,66,<br>bpc-1 | motor and panel side ppm is done.                                                            |
| Radio remote panel for eot-2             | panel installation on eot in under progress.                                                 |
| co-32 pullchord                          | cable joint done at 4 places and restored in circuit.                                        |