

BUILDING SAFETY CERTIFICATE

No. NCR/SSE/WORKS/2024

Dated: 18-06-2024

It is certified that the existing building **North Central Railway College** (name of the building or premises) at **Tundla, Distt Firozabad, UP-283204** (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block-1 (Room no. 21,22,23,24, Principal's Chamber, College Office, CBSE Deptt.)	Block-2 (Biology Lab, Computer Lab, Art room, Music room, Staff room, Room no. 4 to 11)	Block-3 (Room no. 26 to 35, NCC room, Ladies Staff room, Hindi/Lit. room)	Block-4 (Chem. Lab, Physics Lab, Library, Room no. 12, 14 to 17)	Block-5 (College Hall, Exam. Deptt., Confidential Deptt, Games Deptt. Geog, Deptt, Home Sc. Deptt.)	Block-6 (College Games Field)
No. of Floor(s) in the Block	01	01	01	01	01	01

The building is owned/occupied by **North Central Railway College, Tundla** (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **Engg. Deptt./North Central Railway/Tundla** (Name of Department/ Govt.) on **03/06/2024** (date of inspection) in the presence of **Mr. Abdullah Shafiq/ Sr. Section Engg. (Works)/ North Central Railway/ Tundla** (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from **03/06/2024** for a period of **Three** years in accordance with rule and subject to compliance of the specific conditions as appended.

1. As per Railways/Govt. rules
2. As per map/layout of the college
3. *****
4. *****

Issued on 18-06-2024 at **Tundla** by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : _____

Name : _____

Designation : **Sr. Section Engg.**

Name & Address of Department Office.

Sr. Section Engg. (Works)/North Central Railway/Tundla

Principal
N.C.R. COLLEGE
Tundla-Firozabad