



Inspection report, Final: PO003676

KS107287-SWAN: SWAN JEWELRY SET



[Online report](#)

Inspector	QC-JOJO Chen	Inspection Date	Sep 16, 2026
Sample Qty	80	Order Qty	804
Location	29° 21' 13" N x 120° 3' 47" E	Checklist Name	Final
Planned Date	Sep 16, 2026	Sampling Method	AQL 2.5/4 Level II
Supplier Name	10 FASHION		

Inspector Conclusion	Approved
----------------------	----------

SUMMARY

	PO003676:KS107287-SWAN
1 Factory details	
2 Quantity Check	
3 Product	
4 On-site Test	
5 Pack and Packaging	

	CRITICAL	MAJOR	MINOR
F5 Coarse/thick Yarn.	-	-	2
F13 Scratch marks / cracks in surface.	-	-	1
A18 Glue Marks.	-	-	1
F1 Soiling/stains.	-	-	1
TOTAL	0	0	5
AQL MAX	0	5	7

DEFECTS: 5


1	F5 Coarse/thick Yarn. -	MINOR Items affected: 2
---	-------------------------	-----------------------------------



2	F13 Scratch marks / cracks in surface. -	MINOR Items affected: 1
---	--	---



3	A18 Glue Marks. -	MINOR Items affected: 1
---	-------------------	---



4	F1 Soiling/stains. -	MINOR Items affected: 1
---	----------------------	---



CHECKPOINTS: 25

1	Factory details	
---	-----------------	-------------



1.1	Factory name at the location for QC (not supplier name)	OK
-----	---	----

Factory Name:

昊林饰品有限公司

Factory Address:

浙江省义乌市柳青路1569号3号楼5楼左边



2	Quantity Check	
---	----------------	------------------------

2.1	Warehouse / carton piled view	OK
-----	-------------------------------	----



2.2	Production quantity match PO	OK
	Bulk order quantity: 804 sets Bulk packing quantity: 804 sets (Automatic translation)	



3	Product	
---	---------	------------------------

3.1	Product compare against approved sample / color swatch/TECH file	OK
-----	--	----





3.2	Labelling (hangtag, main label, size label, care label, tracking label)	OK
-----	---	----

OS: (804)

Barcode can be scanned	OK
Scanned barcode	5715681418215
Barcode from order data	5715681418215
Scanned format	EAN_13

Barcode can be scanned	OK
Scanned barcode	5715681418222
Barcode from order data	
Scanned format	EAN_13



3.3	Embroidery / Printing check	
3.4	Lace / Trimming / Accessories check	
3.5	Workmanship	OK





3.6	Measurement	OK
	The lengths of the necklaces and bracelets in the bulk order and the confirmed sample are consistent. (Automatic translation)	

	Specification	Tolerance	Actual
	-	-	



4	On-site Test	
4.1	Metal detection	
4.2	Pull test	OK




4.3	Smell check	OK
-----	-------------	----



4.4	Humidity check	
-----	----------------	--

4.5	Garment weight (sweater only)	
-----	-------------------------------	--


4.6	Prove of color fastness test from supplier	OK
-----	--	----



4.7	The product is packed in poly bag or carton. Supplier can't send products without packaging.	OK
-----	--	----



4.8	扣头功能测试	OK
-----	--------	----




5	Pack and Packaging	
---	--------------------	------------------------

5.1	Approved sample/QA file available during inspection	OK
-----	---	----





Confirmation sample provided by the factory






5.2	Export carton (shipping mark, barcode)	OK
-----	--	----

Barcode can be scanned	
Scanned barcode	
Barcode from order data	
Scanned format	




5.3	Export carton (dimension, weight)	OK
-----	-----------------------------------	----

	Specification	Tolerance	Actual
L	-	-	50
W	-	-	35
H	-	-	25
Gross Weight	-	-	6.6



5.4	Carton Packing (quantity, ratio etc), 3 ply carton	OK
-----	--	----





5.5	Inner package (polybag, sticker, tissue paper, silica gel etc)	OK
-----	---	----



5.6	Hanger (quality, size etc)	
-----	----------------------------	--

5.7	Header card	
-----	-------------	--

5.8	Products are in polybags	OK
-----	--------------------------	----

