



Inspection report, Final: PO003423

FA100061-BEIGE: BABY HAIRBRUSH SET 16 PCS IN DISPLAY



[Online report](#)

Inspector	Nya Ni	Inspection Date	May 28, 2026
Sample Qty	80	Order Qty	848
Location	30° 1' 49" N x 121° 21' 2" E	Checklist Name	Final
Planned Date	May 26, 2026	Sampling Method	AQL 2.5/4 Level II
Supplier Name	10 FASHION		

Inspector Conclusion	Rejected	1. The stickers are misplaced. They should be swapped. The Colli sticker should be on the outer cardboard box. The individual stickers should be on the hanging card. 2. The hanging card is missing the ♻️ recycling sticker. (Automatic translation)
----------------------	-----------------	---

SUMMARY

	PO003423:FA100061-BEIGE
1 Factory details	
2 Quantity Check	
3 Product	
3.2 Labelling (hangtag, main label, size label, care label, tracking label)	1
4 On-site Test	
5 Pack and Packaging	

1 The sticker is in the wrong position. They need to be swapped. The Colli sticker should be placed on the outer box.

	CRITICAL	MAJOR	MINOR
T2 Incorrect position.	-	General Defect	-
A5 Unevenness.	-	-	2
WX Other.	-	-	2
W1 Threads, untrimmed.	-	-	1
TOTAL	0	0	5
AQL MAX	0	5	7

DEFECTS: 5

1	T2 Incorrect position. The stickers are misplaced. They should be swapped. The Colli sticker should be on the outer cardboard box. The individual stickers should be on the hanging card. The hanging card is missing the ♻️ recycling sticker. (Automatic translation)	MAJOR General Defect
---	--	-------------------------



2	A5 Unevenness. -	MINOR Items affected: 2
---	------------------	----------------------------



3	WX Other. It has black fur (Automatic translation)	MINOR Items affected: 2
---	---	----------------------------



4	W1 Threads, untrimmed. -	MINOR Items affected: 1
---	--------------------------	----------------------------



CHECKPOINTS: 23


1	Factory details
---	-----------------

1.1	Factory name at the location for QC (not supplier name)
-----	---

Factory Name:

Factory Address:




2	Quantity Check	
2.1	Warehouse / carton piled view	OK
   		
2.2	Production quantity match PO	OK
 The factory provides order details: 848 pieces.		
3	Product	
3.1	Product compare against approved sample / color swatch/TECH file	OK
 		
3.2	Labelling (hangtag, main label, size label, care label, tracking label)	Not OK

OS: (848)	
Barcode can be scanned	OK
Scanned barcode	5715681162699
Barcode from order data	5715681162699
Scanned format	EAN_13

Barcode can be scanned	OK
Scanned barcode	5715681162705
Barcode from order data	
Scanned format	EAN_13

DEFECT T2 Incorrect position. The stickers are misplaced. They should be swapped. The Colli sticker should be on the outer cardboard box. The individual stickers should be on the hanging card. The hanging card is missing the ♻️ recycling sticker.
(Automatic translation)

MAJOR
General Defect



The sticker is in the wrong position. They need to be swapped. The Colli sticker should be placed on the outer box.

3.3 Embroidery / Printing check



3.4	Lace / Trimming / Accessories check
-----	-------------------------------------

3.5	Workmanship
-----	-------------

3.6	Measurement	OK
-----	-------------	----


	Specification	Tolerance	Actual
	-	-	



4	On-site Test	
---	--------------	------------------------

4.1	Metal detection
-----	-----------------

4.2	Pull test
-----	-----------





4.3	Smell check
-----	-------------



4.4	Humidity check
-----	----------------

4.5	Garment weight (sweater only)
-----	-------------------------------

4.6	Prove of color fastness test from supplier	OK
-----	--	----



4.7	Shrinkage test - prove from supplier
-----	--------------------------------------



5	Pack and Packaging	
---	--------------------	------------------------

5.1	Approved sample/QA file available during inspection	OK
-----	---	----



The factory provides inspection samples.

5.2	Export carton (shipping mark, barcode)	OK
-----	--	----

Barcode can be scanned	
Scanned barcode	
Barcode from order data	
Scanned format	



5.3	Export carton (dimension, weight)	OK
-----	-----------------------------------	----

	Specification	Tolerance	Actual
L	-	-	55
W	-	-	45
H	-	-	38

Gross Weight	-	-	9.5
--------------	---	---	-----



5.4	Carton Packing (quantity, ratio etc), 3 ply carton	OK
-----	--	----

5.5	Inner package (polybag, sticker, tissue paper, silica gel etc)	OK
-----	---	----



5.6	Hanger (quality, size etc)	
-----	----------------------------	--

5.7	Header card	
-----	-------------	--

COMMENTS

Nya Ni Inspector's conclusion May 28, 2026 14:19

1. The stickers are misplaced. They should be swapped. The Colli sticker should be on the outer cardboard box. The individual stickers should be on the hanging card.
 2. The hanging card is missing the  recycling sticker.
-