



Inspection report, Final: PO003221

KS103669-PINK: ALL I WISH FOR - JEWELRY



[Online report](#)

Inspector	Sunny Chen	Inspection Date	May 11, 2026
Sample Qty	80	Order Qty	1176
Location	29° 21' 13" N x 120° 3' 48" E	Checklist Name	Final
Planned Date	May 11, 2026	Sampling Method	AQL 2.5/4 Level II
Supplier Name	10 FASHION		

Inspector Conclusion	Approved
----------------------	----------

SUMMARY

	PO003221:KS103669-PINK
1 Factory details	
2 Quantity Check	
3 Product	
4 On-site Test	
5 Pack and Packaging	

	CRITICAL	MAJOR	MINOR
WX Other.	-	1	-
W3 Stitch, Broken or defect.	-	1	-
F7 Damaged fabric.	-	1	-
A5 Unevenness.	-	1	-
F1 Soiling/stains.	-	-	2
TOTAL	0	4	2
AQL MAX	0	5	7

DEFECTS: 6

1	WX Other. sharp (Automatic translation)	MAJOR Items affected: 1
---	--	----------------------------



2	W3 Stitch, Broken or defect. -	MAJOR Items affected: 1
---	--------------------------------	----------------------------



3	F7 Damaged fabric. -	MAJOR Items affected: 1
---	----------------------	----------------------------



4	A5 Unevenness. -	MAJOR Items affected: 1
---	------------------	----------------------------



5	F1 Soiling/stains. Dirty corpus cavernosum (Automatic translation)	MINOR Items affected: 2
---	--	----------------------------



CHECKPOINTS: 24

1	Factory details	
1.1	Factory name at the location for QC (not supplier name)	OK

Factory Name:

义乌市昊林饰品厂

Factory Address:

浙江省义乌市柳青路



The factory is located on the 5th floor of the building.



Brand



workshop



Container area

2	Quantity Check	
---	----------------	-------------

2.1	Warehouse / carton piled view	OK
	Factory box yield rate: 90% (Automatic translation)	



Stacked container photos



Box Photo

2.2	Production quantity match PO	OK
	Order quantity: 1176 pieces Packing list: 1176 pieces Quantity matches (Automatic translation)	



Order



Packing list

3	Product	
---	---------	-------------

3.1	Product compare against approved sample / color swatch/TECH file	OK
	The bulk order is OK compared with the confirmed sample provided by the factory. (Automatic translation)	



3.2	Labelling (hangtag, main label, size label, care label, tracking label)	OK
-----	---	----



OS: (1176)

Barcode can be scanned	OK
Scanned barcode	5715681100134
Barcode from order data	5715681100134
Scanned format	EAN_13

Size: KSOS

Barcode can be scanned	OK
Scanned barcode	5715681100141
Barcode from order data	
Scanned format	EAN_13





3.3 Embroidery / Printing check

3.4 Lace / Trimming / Accessories check

3.5 Workmanship

3.6 Measurement

	Specification	Tolerance	Actual
	-	-	

4 On-site Test

4.1 Metal detection

4.2 Pull test


OK

Manual tensile test OK
(Automatic translation)







4.3	Smell check	OK
The artificial olfactory odor test was OK; there was no pungent odor, which is acceptable. (Automatic translation)		



4.4	Humidity check	
-----	----------------	--

4.5	Garment weight (sweater only)	
-----	-------------------------------	--

4.6	Prove of color fastness test from supplier	OK
-----	--	----



4.7	The product is packed in poly bag or carton. Supplier can't send products without packaging.	OK
-----	--	----



Outer box shape

5	Pack and Packaging	
---	--------------------	--

5.1	Approved sample/QA file available during inspection	OK
	There are confirmation samples, orders, packing lists, and barcode information provided by the factory. (Automatic translation)	



Confirmation sample provided by the factory




Confirmation sample



Order



Packing list




Barcode data

5.2	Export carton (shipping mark, barcode)	OK
	The outer box does not require a barcode sticker; the box has markings on all four sides, the location and contents of which are shown in the image below; the front of the box has an environmental protection logo printed on it. (Automatic translation)	

Barcode can be scanned	
Scanned barcode	
Barcode from order data	
Scanned format	



Outer box shape



Front box label



Side box markings

5.3	Export carton (dimension, weight)	OK
-----	-----------------------------------	----

	Specification	Tolerance	Actual
L	-	-	49

W	-	-	40
H	-	-	19.5
Gross Weight	-	-	8.6



Carton length



width



high



Gross weight



Gross weight

5.4	Carton Packing (quantity, ratio etc), 3 ply carton	OK
	The quantity per carton is based on the packing list provided by the factory. Each carton contains 24 pieces. (Automatic translation)	



Packing list



Outer box shape



5.5	Inner package (polybag, sticker, tissue paper, silica gel etc)	OK
	Colli inner packaging (6 pieces); Jewelry box inner packaging (two sets, instruction manual). (Automatic translation)	



Colli cardboard packaging



Colli inner packaging 6 pieces



Single-piece cardboard box packaging



Individual inner packaging jewelry box



Open the jewelry box; you'll find two sets and an instruction manual.

5.6	Hanger (quality, size etc)
-----	----------------------------

5.7	Header card
-----	-------------

5.8	Products are in polybags
-----	--------------------------