Inspection report, Final: PO001943

KS104454-SIROCCO: TUT WALLET

Online report

Inspector	Wing Xu	Inspection Date	Jun 30, 2025
Sample Qty	125	Order Qty	1764
Location	23° 27' 56" N x 113° 9' 49" E	Checklist Name	Final
Planned Date	Jun 29, 2025	Sampling Method	AQL 2.5/4 Level II
Supplier Name	10 FASHION		

Inspector Conclusion	Approved	

SUMMARY

	PO001943:KS104454-SIROCCO
1 Factory details	
2 Quantity Check	
3 Product	
3.5 Workmanship	
4 On-site Test	
5 Pack and Packaging	

	CRITICAL	MAJOR	MINOR
W1 Threads, untrimmed.	-	1	-
M5 Damaged fabric / material.	-	1	-
W1 Threads, untrimmed.	-	-	1
W1 Threads, untrimmed.	-	-	1
M1 Soiling/stains.	-	-	1
W1 Threads, untrimmed.	-	-	1
M1 Soiling/stains.	-	-	1
W1 Threads, untrimmed.	-	-	1
M1 Soiling/stains.	-	-	1
TOTAL	**0**	**2**	**7**
AQL MAX	**0**	**7**	**10**

DEFECTS: 9

1	W1 Threads, untrimmed. thread end	MAJOR Items affected: 1



2	M5 Damaged fabric / material. the sewing lable damage	MAJOR Items affected: 1

3	W1 Threads, untrimmed. thread end	MINOR Items affected: 1

4	W1 Threads, untrimmed. thread end	MINOR Items affected: 1

5	M1 Soiling/stains. dirty stain	MINOR Items affected: 1

6	W1 Threads, untrimmed. thread end	MINOR Items affected: 1

7	M1 Soiling/stains. dirty stain	MINOR Items affected: 1

8	W1 Threads, untrimmed. thread end	MINOR Items affected: 1

9	M1 Soiling/stains. dirty stain	MINOR Items affected: 1

CHECKPOINTS: 23

1	Factory details	

1.1	Factory name at the location for QC (not supplier name)	OK

Factory Name:	格调皮具
Factory Address:	广东省广州市花都区狮岭镇则斌路 7 号

2	**Quantity Check**	

2.1	**Warehouse / carton piled view**	**OK**

2.2	**Production quantity match PO**	**OK**
	products finished 100%	

3	**Product**	

3.1	**Product compare against approved sample / color swatch/TECH file**	**OK**





3.2	**Labelling (hangtag, main label, size label, care label, tracking label)**	**OK**

innercarton

Barcode can be scanned	OK
Scanned barcode	5715681160602
Barcode from order data	
Scanned format	EAN_13

product

Barcode can be scanned	OK
Scanned barcode	5715681160619
Barcode from order data	
Scanned format	EAN_13

3.3	Embriodery / Printing check	OK

3.4	Lace / Trimming / Accessories check

3.5	Workmanship	Not OK

DEFECT W1 Threads, untrimmed. thread end

MAJOR
Items affected: 1



DEFECT M5 Damaged fabric / material. the sewing lable damage

MAJOR
Items affected: 1

DEFECT W1 Threads, untrimmed. thread end

MINOR
Items affected: 1

DEFECT W1 Threads, untrimmed. thread end

MINOR
Items affected: 1

DEFECT M1 Soiling/stains. dirty stain

MINOR
Items affected: 1

DEFECT W1 Threads, untrimmed. thread end

MINOR
Items affected: 1

DEFECT M1 Soiling/stains. dirty stain

MINOR
Items affected: 1

DEFECT W1 Threads, untrimmed. thread end

MINOR
Items affected: 1

DEFECT M1 Soiling/stains. dirty stain

MINOR
Items affected: 1

3.6	Measurement	OK

Measurement-OS	Specification	Tolerance	Actual
A: WIDTH (cm)	9.50	-	9.5
B: DEPTH (cm)	2.00	-	2.5

4	On-site Test	

4.1	Metal detection

4.2	Pull test	OK



4.3	Smell check	OK



4.4	Humidity check

4.5	Garment weight (sweater only)

4.6	Prove of color fastness test from supplier	OK



4.7	The product is packed in poly bag or carton. Supplier can't send products without packaging.	OK

5	Pack and Packaging	

5.1	Approved sample/QA file available during inspection	OK

5.2	Export carton (shipping mark, barcode)	OK

Barcode can be scanned	

Scanned barcode	
Barcode from order data	
Scanned format	



5.3	**Export carton (dimension, weight)**	**OK**

	Specification	Tolerance	Actual
L	-	-	30.5
W	-	-	29
H	-	-	36
Gross Weight	-	-	4.43

5.4	**Carton Packing (quantity, ratio etc), 3 ply carton**	**OK**



5.5	Inner package (polybag, sticker, tissue paper, silica gel etc)	OK

5.6	Hanger (quality, size etc)

5.7	Header card	OK