Inspection report, Final: PO000806

KS103729-MISTY ROSE: BONNIE RINGS

Online report

Inspector	Wing Xu	Inspection Date	May 26, 2025
Sample Qty	80	Order Qty	1002
Location	29° 21' 11" N x 120° 3' 48" E	Checklist Name	Final
Planned Date	May 25, 2025	Sampling Method	AQL 2.5/4 Level II
Supplier Name	10 FASHION		

Inspector Conclusion	Approved

SUMMARY

	PO000806:KS103729-MISTY ROSE
1 Factory details	
2 Quantity Check	
3 Product	
3.5 Workmanship	
4 On-site Test	
5 Pack and Packaging	

	CRITICAL	MAJOR	MINOR
A8 Glue Marks.	-	1	-
P7 Incorrect packaging.	-	1	-
M5 Damaged fabric / material.	-	-	1
A8 Glue Marks.	-	-	1
M5 Damaged fabric / material.	-	-	1
M5 Damaged fabric / material.	-	-	1
M5 Damaged fabric / material.	-	-	1
M5 Damaged fabric / material.	-	-	1
M5 Damaged fabric / material.	-	-	1
TOTAL	**0**	**2**	**7**
AQL MAX	**0**	**5**	**7**

DEFECTS: 9

1	A8 Glue Marks. handle off	MAJOR Items affected: 1

2	P7 Incorrect packaging. lable wrinkle	MAJOR Items affected: 1

3	M5 Damaged fabric / material. scratch mark	MINOR Items affected: 1

4	A8 Glue Marks. glue mark	MINOR Items affected: 1

5	**M5 Damaged fabric / material. scratch mark**	MINOR Items affected: 1

6	**M5 Damaged fabric / material. scratch mark**	MINOR Items affected: 1

7	**M5 Damaged fabric / material. scratch mark**	MINOR Items affected: 1

8	**M5 Damaged fabric / material. scratch mark**	MINOR Items affected: 1

9	M5 Damaged fabric / material. scratch mark	MINOR Items affected: 1

CHECKPOINTS: 23

1	Factory details	

1.1	Factory name at the location for QC (not supplier name)	OK

Factory Name:	义乌萌宣贸易公司
Factory Address:	浙江省金华市义乌市柳青路 1565 号

2	Quantity Check	

2.1	Warehouse / carton piled view	OK

2.2	Production quantity match PO	OK
	product finished 100%	

3	Product	

3.1	Product compare against approved sample / color swatch/TECH file	OK



3.2	Labelling (hangtag, main label, size label, care label, tracking label)	OK

inner bag

Barcode can be scanned	OK
Scanned barcode	5715681104811
Barcode from order data	
Scanned format	EAN_13

product

Barcode can be scanned	OK
Scanned barcode	5715681104828
Barcode from order data	
Scanned format	EAN_13



3.3	Embriodery / Printing check

3.4	Lace / Trimming / Accessories check

3.5	Workmanship	Not OK

DEFECT A8 Glue Marks. handle off

MAJOR
Items affected: 1

DEFECT P7 Incorrect packaging. lable wrinkle

MAJOR
Items affected: 1

DEFECT M5 Damaged fabric / material. scratch mark

MINOR
Items affected: 1

DEFECT A8 Glue Marks. glue mark

MINOR
Items affected: 1

DEFECT M5 Damaged fabric / material. scratch mark

MINOR
Items affected: 1

DEFECT M5 Damaged fabric / material. scratch mark

MINOR
Items affected: 1

DEFECT M5 Damaged fabric / material. scratch mark

MINOR
Items affected: 1

DEFECT M5 Damaged fabric / material. scratch mark

MINOR
Items affected: 1

DEFECT M5 Damaged fabric / material. scratch mark

MINOR
Items affected: 1

3.6	Measurement

	Specification	Tolerance	Actual
	-	-	

4	On-site Test	

4.1	Metal detection

4.2	Pull test	OK

4.3	Smell check	OK



4.4	Humidity check

4.5	Garment weight (sweater only)	

4.6	Prove of color fastness test from supplier	OK





4.7	The product is packed in poly bag or carton. Supplier can't send products without packaging.	OK

5	Pack and Packaging	

5.1	Approved sample/QA file available during inspection	OK



5.2	Export carton (shipping mark, barcode)	OK

Barcode can be scanned	
Scanned barcode	
Barcode from order data	
Scanned format	





5.3	**Export carton (dimension, weight)**	**OK**

	Specification	Tolerance	Actual
L	-	-	55
W	-	-	40
H	-	-	51
Gross Weight	-	-	16.1

5.4	**Carton Packing (quantity, ratio etc), 3 ply carton**	**OK**



5.5	Inner package (polybag, sticker, tissue paper, silica gel etc)	OK









5.6	Hanger (quality, size etc)

5.7	Header card