Inspection report, Final: PO000806

KS103876-PINK GLITTER: LOVE LETTER WALLET

Online report

Inspector	Wing Xu	Inspection Date	-
Sample Qty	125	Order Qty	1248
Location	29° 23' 44" N x 120° 7' 55" E	Checklist Name	Final
Planned Date	May 13, 2025	Sampling Method	AQL 2.5/4 Level II
Supplier Name	10 FASHION		

Inspector Conclusion	Approved	

Status: **Pending**

SUMMARY

	PO000806:KS103876-PINK GLITTER
1 Factory details	
2 Quantity Check	
3 Product	
3.5 Workmanship	!
4 On-site Test	
5 Pack and Packaging	

	CRITICAL	MAJOR	MINOR
W1 Threads, untrimmed.	-	1	-
W1 Threads, untrimmed.	-	1	-
W1 Threads, untrimmed.	-	-	5
W1 Threads, untrimmed.	-	-	1
W1 Threads, untrimmed.	-	-	1
TOTAL	**0**	**2**	**7**
AQL MAX	**0**	**7**	**10**

DEFECTS: 9

1	**W1 Threads, untrimmed. loop thread**	MAJOR Items affected: 1



2	W1 Threads, untrimmed. foreign thread inside the bag	MAJOR Items affected: 1

3	W1 Threads, untrimmed. thread end	MINOR Items affected: 5

4	W1 Threads, untrimmed. thread end	MINOR Items affected: 1

5	W1 Threads, untrimmed. thread end	MINOR Items affected: 1



CHECKPOINTS: 23

1	Factory details	

1.1	Factory name at the location for QC (not supplier name)	OK

Factory Name:	义乌泰源皮具有限公司
Factory Address:	义乌市苏溪镇苏新街 29 号 1 号楼三楼

2	**Quantity Check**	

2.1	**Warehouse / carton piled view**	**OK**

2.2	**Production quantity match PO**	**OK**
	product finished 100%	

3	**Product**	

3.1	**Product compare against approved sample / color swatch/TECH file**	**OK**

3.2	**Labelling (hangtag, main label, size label, care label, tracking label)**	**OK**

polybag

Barcode can be scanned	OK
Scanned barcode	5715681118528
Barcode from order data	

Scanned format	EAN_13

product

Barcode can be scanned	OK
Scanned barcode	5715681118535
Barcode from order data	
Scanned format	EAN_13

colour card

Barcode can be scanned	OK
Scanned barcode	5715681118535
Barcode from order data	
Scanned format	EAN_13





3.3	**Embriodery / Printing check**	**OK**

3.4	Lace / Trimming / Accessories check

3.5	Workmanship	Not OK

DEFECT W1 Threads, untrimmed. loop thread

MAJOR
Items affected: 1



DEFECT W1 Threads, untrimmed. foreign thread inside the bag

MAJOR
Items affected: 1

DEFECT W1 Threads, untrimmed. thread end

MINOR
Items affected: 1

DEFECT W1 Threads, untrimmed. thread end

MINOR
Items affected: 1



DEFECT W1 Threads, untrimmed. thread end

MINOR
Items affected: 5

3.6	Measurement

	Specification	Tolerance	Actual
	-	-	

4	On-site Test	

4.1	Metal detection

4.2	Pull test	OK



4.3	Smell check	OK

4.4	Humidity check

4.5	Garment weight (sweater only)

4.6	Prove of color fastness test from supplier	OK





4.7	The product is packed in poly bag or carton. Supplier can't send products without packaging.	OK

5	Pack and Packaging	

5.1	Approved sample/QA file available during inspection	OK



5.2	Export carton (shipping mark, barcode)	OK

Barcode can be scanned	
Scanned barcode	
Barcode from order data	
Scanned format	

5.3	Export carton (dimension, weight)	OK

	Specification	Tolerance	Actual
L	-	-	58
W	-	-	40
H	-	-	38
Gross Weight	-	-	13.75



5.4	Carton Packing (quantity, ratio etc), 3 ply carton	OK

5.5	Inner package (polybag, sticker, tissue paper, silica gel etc)	OK

5.6	Hanger (quality, size etc)

5.7	Header card	OK