Inspection report, Final: PO003087

KS105567-MELLOW ROSE: TUT WALLET

Online report

Inspector	Wing Xu	Inspection Date	Dec 18, 2025
Sample Qty	80	Order Qty	882
Location	23° 28' 17" N x 113° 12' 41" E	Checklist Name	Final
Planned Date	Dec 17, 2025	Sampling Method	AQL 2.5/4 Level II
Supplier Name	10 FASHION		

Inspector Conclusion	Approved

SUMMARY

	PO003087:KS105567-MELLOW ROSE
1 Factory details	
2 Quantity Check	
3 Product	
3.5 Workmanship	
4 On-site Test	
5 Pack and Packaging	

	CRITICAL	MAJOR	MINOR
W1 Threads, untrimmed.	-	-	1
W9 Seam Type.	-	-	1
W8 Uneven stitches.	-	-	1
W1 Threads, untrimmed.	-	-	1
TOTAL	**0**	**0**	**4**
AQL MAX	**0**	**5**	**7**

DEFECTS: 4

1	**W1 Threads, untrimmed. thread end**	MINOR Items affected: 1

2	W9 Seam Type. the sewing lable is not aligned	MINOR Items affected: 1

3	W8 Uneven stitches. wrinkle	MINOR Items affected: 1



4	W1 Threads, untrimmed. thread end	MINOR Items affected: 1

CHECKPOINTS: 23

1	Factory details	

1.1	Factory name at the location for QC (not supplier name)	OK

Factory Name:	广州迅悦箱包有限公司
Factory Address:	广东省广州市花都区狮岭镇育才路 12 号 1 栋 5 楼

2	**Quantity Check**	

2.1	**Warehouse / carton piled view**	**OK**

2.2	**Production quantity match PO**	**OK**
	products finished 100%	

3	**Product**	

3.1	**Product compare against approved sample / color swatch/TECH file**	**OK**

3.2	**Labelling (hangtag, main label, size label, care label, tracking label)**	**OK**

OS: (882)

Barcode can be scanned	OK
Scanned barcode	5715681279809
Barcode from order data	5715681279809
Scanned format	EAN_13

product

Barcode can be scanned	OK
Scanned barcode	5715681279816
Barcode from order data	
Scanned format	EAN_13





3.3	Embriodery / Printing check

3.4	Lace / Trimming / Accessories check

3.5	Workmanship	Not OK

DEFECT W1 Threads, untrimmed. thread end

MINOR
Items affected: 1

DEFECT W9 Seam Type. the sewing lable is not aligned

MINOR
Items affected: 1

DEFECT W8 Uneven stitches. wrinkle

MINOR
Items affected: 1



DEFECT W1 Threads, untrimmed. thread end

MINOR
Items affected: 1

3.6	**Measurement**	**OK**

Measurement-OS	Specification	Tolerance	Actual
A: WIDTH (cm)	9.50	-	9.5
B: DEPTH (cm)	2.00	-	2



4	On-site Test	

4.1	Metal detection

4.2	Pull test	OK



4.3	Smell check	OK

4.4	Humidity check

4.5	Garment weight (sweater only)

4.6	Prove of color fastness test from supplier	OK

5	Pack and Packaging	

5.1	Approved sample/QA file available during inspection	OK

5.2	Export carton (shipping mark, barcode)	OK

Barcode can be scanned	
Scanned barcode	
Barcode from order data	
Scanned format	





5.3	Export carton (dimension, weight)	OK

	Specification	Tolerance	Actual
L	-	-	29.5
W	-	-	30
H	-	-	34
Gross Weight	-	-	4.5



5.4	Carton Packing (quantity, ratio etc), 3 ply carton	OK

5.5	Inner package (polybag, sticker, tissue paper, silica gel etc)	OK

5.6	Hanger (quality, size etc)

5.7	Header card

5.8	Products are in polybags	OK