Inspection report, Final: PO000806

KS103861-MULTI: LITTLE NECKLACE BOX DISPLAY 24 PCS

Online report

Inspector	Wing Xu	Inspection Date	May 14, 2025
Sample Qty	125	Order Qty	1224
Location	29° 21' 12" N x 120° 3' 47" E	Checklist Name	Final
Planned Date	May 13, 2025	Sampling Method	AQL 2.5/4 Level II
Supplier Name	10 FASHION		

Inspector Conclusion	Approved

SUMMARY

	PO000806:KS103861-MULTI
1 Factory details	
2 Quantity Check	
3 Product	
3.5 Workmanship	
4 On-site Test	
5 Pack and Packaging	

	CRITICAL	MAJOR	MINOR
M5 Damaged fabric / material.	-	1	-
M5 Damaged fabric / material.	-	1	-
TOTAL	**0**	**2**	**0**
AQL MAX	**0**	**7**	**10**

DEFECTS: 2

1	**M5 Damaged fabric / material. the necklace broken**	MAJOR Items affected: 1

2	M5 Damaged fabric / material. burrs	MAJOR Items affected: 1



CHECKPOINTS: 23

1	Factory details	

1.1	Factory name at the location for QC (not supplier name)	OK

Factory Name:	义乌萌宣贸易有限公司
Factory Address:	浙江省金华市义乌市后宅街道柳青路1565号403

2	Quantity Check	

2.1	Warehouse / carton piled view	OK

2.2	Production quantity match PO	OK
	product finished 100%	

3	Product	

3.1	Product compare against approved sample / color swatch/TECH file	OK

















3.2	**Labelling (hangtag, main label, size label, care label, tracking label)**	**OK**

colour bo x

Barcode can be scanned	OK
Scanned barcode	5715681116371
Barcode from order data	
Scanned format	EAN_13

colour box

Barcode can be scanned	OK
Scanned barcode	5715681116388
Barcode from order data	
Scanned format	EAN_13



3.3	**Embriodery / Printing check**

3.4	**Lace / Trimming / Accessories check**

3.5	**Workmanship**	**Not OK**

DEFECT M5 Damaged fabric / material. the necklace broken

MAJOR
Items affected: 1

DEFECT M5 Damaged fabric / material. burrs

MAJOR
Items affected: 1



3.6	Measurement

	Specification	Tolerance	Actual
	-	-	

4	On-site Test	

4.1	Metal detection

4.2	Pull test	OK

4.3	Smell check	OK

4.4	Humidity check

4.5	Garment weight (sweater only)	

4.6	Prove of color fastness test from supplier	OK





4.7	function test	OK

5	Pack and Packaging	

5.1	Approved sample/QA file available during inspection	OK

5.2	Export carton (shipping mark, barcode)	OK

Barcode can be scanned	
Scanned barcode	
Barcode from order data	
Scanned format	





5.3	**Export carton (dimension, weight)**	**OK**

	Specification	Tolerance	Actual
L	-	-	49
W	-	-	40
H	-	-	35
Gross Weight	-	-	10.8



5.4	**Carton Packing (quantity, ratio etc), 3 ply carton**	**OK**

5.5	**Inner package (polybag, sticker, tissue paper, silica gel etc)**	**OK**



5.6	**Hanger (quality, size etc)**

5.7	**Header card**