Inspection report, Final: PO000806

KS101921-BARBADOS CHERRY: CHERRY WALLET BAG

Online report

Inspector	Wing Xu	Inspection Date	-
Sample Qty	80	Order Qty	1116
Location	29° 23' 43" N x 120° 7' 55" E	Checklist Name	Final
Planned Date	May 13, 2025	Sampling Method	AQL 2.5/4 Level II
Supplier Name	10 FASHION		

Inspector Conclusion	Approved	

Status: **Pending**

SUMMARY

	PO000806:KS101921-BARBADOS CHERRY
1 Factory details	
2 Quantity Check	
3 Product	
3.5 Workmanship	
4 On-site Test	
5 Pack and Packaging	

	CRITICAL	MAJOR	MINOR
M3 Broken Yarn.	-	1	-
M5 Damaged fabric / material.	-	-	3
W1 Threads, untrimmed.	-	-	1
W1 Threads, untrimmed.	-	-	1
W1 Threads, untrimmed.	-	-	1
W1 Threads, untrimmed.	-	-	1
W1 Threads, untrimmed.	-	-	1
TOTAL	**0**	**1**	**8**
AQL MAX	**0**	**5**	**7**

DEFECTS: 9

1	M3 Broken Yarn. the strap broken	MAJOR Items affected: 1

2	M5 Damaged fabric / material. poor fabric	MINOR Items affected: 3

3	W1 Threads, untrimmed. thread end	MINOR Items affected: 1

4	W1 Threads, untrimmed. thread end	MINOR Items affected: 1

5	W1 Threads, untrimmed. thread end	MINOR Items affected: 1

6	W1 Threads, untrimmed. thread end	MINOR Items affected: 1

7	W1 Threads, untrimmed. thread end	MINOR Items affected: 1

CHECKPOINTS: 23

1	Factory details	

1.1	Factory name at the location for QC (not supplier name)	OK

Factory Name: 义乌泰源皮具有限公司

Factory Address: 义乌市苏溪镇苏新街 29 号 1 号楼三楼

2	Quantity Check	

2.1	Warehouse / carton piled view	OK

2.2	Production quantity match PO	OK
	products finished 100%	

3	Product	

3.1	Product compare against approved sample / color swatch/TECH file	OK

3.2	Labelling (hangtag, main label, size label, care label, tracking label)	OK

polybag

Barcode can be scanned	OK
Scanned barcode	5715404340151
Barcode from order data	
Scanned format	EAN_13

inner polybag

Barcode can be scanned	OK
Scanned barcode	5715404342001
Barcode from order data	
Scanned format	EAN_13

colour card

Barcode can be scanned	OK
Scanned barcode	5715404342001

Barcode from order data	
Scanned format	EAN_13







3.3	Embriodery / Printing check	OK

3.4	Lace / Trimming / Accessories check

3.5	Workmanship	Not OK

DEFECT M3 Broken Yarn. the strap broken

MAJOR
Items affected: 1

DEFECT W1 Threads, untrimmed. thread end

MINOR
Items affected: 1

DEFECT W1 Threads, untrimmed. thread end

MINOR
Items affected: 1

DEFECT W1 Threads, untrimmed. thread end

MINOR
Items affected: 1

DEFECT W1 Threads, untrimmed. thread end

MINOR
Items affected: 1

DEFECT W1 Threads, untrimmed. thread end

MINOR
Items affected: 1



DEFECT M5 Damaged fabric / material. poor fabric

MINOR
Items affected: 3

3.6	Measurement	OK

Measurement-OS	Specification	Tolerance	Actual
A: WIDTH (cm)	17.50	-	17.5
C: STRAP LENGTH (cm)	74.00	-	72.5

Measurement-OS	Specification	Tolerance	Actual
A: WIDTH (cm)	17.50	-	17.5

C: STRAP LENGTH (cm)	74.00	-	72.5

Measurement-OS	Specification	Tolerance	Actual
A: WIDTH (cm)	17.50	-	17.5
C: STRAP LENGTH (cm)	74.00	-	72.5

4	On-site Test	

4.1	Metal detection

4.2	Pull test	OK





4.3	Smell check	OK



4.4	Humidity check

4.5	Garment weight (sweater only)

4.6	Prove of color fastness test from supplier	OK





4.7	The product is packed in poly bag or carton. Supplier can't send products without packaging.	OK

5	Pack and Packaging	

5.1	Approved sample/QA file available during inspection	OK



5.2	**Export carton (shipping mark, barcode)**	**OK**

Barcode can be scanned	
Scanned barcode	
Barcode from order data	
Scanned format	





5.3	**Export carton (dimension, weight)**	**OK**

	Specification	Tolerance	Actual
L	-	-	52
W	-	-	40
H	-	-	30
Gross Weight	-	-	12.95

5.4	**Carton Packing (quantity, ratio etc), 3 ply carton**	**OK**

5.5	Inner package (polybag, sticker, tissue paper, silica gel etc)	OK

5.6	Hanger (quality, size etc)

5.7	Header card