Inspection report, Final: PO001324

FA100017-BEIGE: BABY HAIRBRUSH SET

Online report

Inspector	Nya Ni	Inspection Date	May 30, 2025
Sample Qty	125	Order Qty	2152
Location	29° 58' 23" N x 121° 26' 6" E	Checklist Name	Final
Planned Date	May 30, 2025	Sampling Method	AQL 2.5/4 Level II
Supplier Name	10 FASHION		

Inspector Conclusion	**Pending**	1. There is a layer of film on the surface of the comb that looks uneven and has bubbles. (Automatic translation)

SUMMARY

	PO001324:FA100017-BEIGE
1 Factory details	
2 Quantity Check	
3 Product	
4 On-site Test	
5 Pack and Packaging	

	CRITICAL	MAJOR	MINOR
F12 Pilling - bobbling.	-	General Defect	-
T5 Defect trim.	-	1	-
T5 Defect trim.	-	-	2
F12 Pilling - bobbling.	-	-	1
F1 Soiling/stains.	-	-	1
TOTAL	**0**	**1**	**4**
AQL MAX	**0**	**7**	**10**

DEFECTS: 5

1	**F12 Pilling - bobbling. -**	MAJOR General Defect



2	T5 Defect trim. -	MAJOR Items affected: 1

3	T5 Defect trim. -	MINOR Items affected: 2

4	F12 Pilling - bobbling. -	MINOR Items affected: 1



5	F1 Soiling/stains. -	MINOR Items affected: 1



CHECKPOINTS: 23

1	Factory details

1.1	Factory name at the location for QC (not supplier name)

Factory Name:

Factory Address:

2	Quantity Check	

2.1	Warehouse / carton piled view	OK

2.2	Production quantity match PO	OK

Factory provides order details 2152Pcs

3	Product	

3.1	Labelling (hangtag, main label, size label, care label, tracking label)	OK

Card inspection

Printed logo check

3.2	Embriodery / Printing check

3.3	Lace / Trimming / Accessories check

3.4	Workmanship

3.5	Measurement	OK

	Specification	Tolerance	Actual
	-	-	

Length 15cm

Width 4cm

Width 2cm

High 2cm

Length 13cm

Length 13.5cm

Width 2.5cm

Width 3.3cm

4	**On-site Test**	

4.1	**Metal detection**

4.2	**Pull test**



4.3	**Smell check**	**OK**

Slight wool smell

4.4	Humidity check

4.5	Garment weight (sweater only)

4.6	Prove of color fastness test from supplier



4.7	Shrinkage test - prove from supplier	OK







4.8	The product is packed in poly bag or carton. Supplier can't send products without packaging.	OK



5	**Pack and Packaging**	

5.1	**Approved sample/QA file available during inspection**	**OK**

Factory provides inspection samples

5.2	**Export carton (shipping mark, barcode)**

Barcode can be scanned	
Scanned barcode	
Barcode from order data	
Scanned format	

5.3	**Export carton (dimension, weight)**	**OK**

	Specification	Tolerance	Actual
L	-	-	61

W	-	-	25
H	-	-	38
Gross Weight	-	-	10.6

5.4	**Carton Packing (quantity, ratio etc), 3 ply carton**	**OK**

5.5	**Inner package (polybag, sticker, tissue paper, silica gel etc)**	**OK**

5.6	**Hanger (quality, size etc)**

5.7	**Header card**

COMMENTS

Nya Ni Inspector's conclusion May 30, 2025 16:13

1. There is a layer of film on the surface of the comb that looks uneven and has bubbles.