Inspection report, Final: PO002747

KS104822-STRAWBERRY: FRAISE WALLET

Online report

Inspector	Wing Xu	Inspection Date	Sep 26, 2025
Sample Qty	80	Order Qty/Available	1152/804
Location	23° 28' 17" N x 113° 12' 41" E	Checklist Name	Final
Planned Date	Sep 24, 2025	Sampling Method	AQL 2.5/4 Level II
Supplier Name	10 FASHION		

Inspector Conclusion	Approved	Confirmed with the factory, the order quantity is 804 pcs, the system quantity is incorrect.

SUMMARY

	PO002747:KS104822-STRAWBERRY
1 Factory details	
2 Quantity Check	
3 Product	
3.5 Workmanship	
4 On-site Test	
5 Pack and Packaging	

	CRITICAL	MAJOR	MINOR
W1 Threads, untrimmed.	-	1	-
W1 Threads, untrimmed.	-	-	1
W1 Threads, untrimmed.	-	-	1
W5 Seam slippage.	-	-	1
TOTAL	**0**	**1**	**3**
AQL MAX	**0**	**5**	**7**

DEFECTS: 4

1	**W1 Threads, untrimmed. loop thread**	MAJOR Items affected: 1

2	W1 Threads, untrimmed. thread end	MINOR Items affected: 1

3	W1 Threads, untrimmed. thread end	MINOR Items affected: 1

4	W5 Seam slippage. stitch loosen	MINOR Items affected: 1

CHECKPOINTS: 23

1	Factory details	

1.1	Factory name at the location for QC (not supplier name)	OK

Factory Name:	广州迅悦箱包有限公司
Factory Address:	广东省广州市花都区狮岭镇育才路 12 号 1 栋 5 楼



2	Quantity Check	

2.1	Warehouse / carton piled view	OK

2.2	Production quantity match PO	OK
	products finished 804pcs， 100%finished	

3	Product	

3.1	Product compare against approved sample / color swatch/TECH file	OK

3.2	**Labelling (hangtag, main label, size label, care label, tracking label)**	**OK**

OS: (1152)

Barcode can be scanned	OK
Scanned barcode	5715681196137
Barcode from order data	5715681196137
Scanned format	EAN_13

product

Barcode can be scanned	OK
Scanned barcode	5715681196144
Barcode from order data	
Scanned format	EAN_13



3.3	**Embriodery / Printing check**	**OK**

3.4	Lace / Trimming / Accessories check

3.5	Workmanship	Not OK

DEFECT W1 Threads, untrimmed. loop thread

MAJOR
Items affected: 1

DEFECT W1 Threads, untrimmed. thread end

MINOR
Items affected: 1

DEFECT W1 Threads, untrimmed. thread end

MINOR
Items affected: 1

DEFECT W5 Seam slippage. stitch loosen

MINOR
Items affected: 1

3.6	Measurement	OK

Measurement-OS	Specification	Tolerance	Actual
height (cm)	8.00	-	8
depth (cm)	1.80	-	1.8

4	On-site Test	

4.1	Metal detection

4.2	Pull test	OK

4.3	Smell check	OK

4.4	Humidity check

4.5	Garment weight (sweater only)

4.6	Prove of color fastness test from supplier	OK



4.7	The product is packed in poly bag or carton. Supplier can't send products without packaging.	OK

5	Pack and Packaging	

5.1	Approved sample/QA file available during inspection	OK

5.2	**Export carton (shipping mark, barcode)**	**OK**

Barcode can be scanned	
Scanned barcode	
Barcode from order data	
Scanned format	





5.3	**Export carton (dimension, weight)**	**OK**

	Specification	Tolerance	Actual
L	-	-	50
W	-	-	21.5
H	-	-	28
Gross Weight	-	-	4.4



5.4	**Carton Packing (quantity, ratio etc), 3 ply carton**	**OK**

5.5	Inner package (polybag, sticker, tissue paper, silica gel etc)	OK

5.6	Hanger (quality, size etc)

5.7	Header card	OK

ARTICLE HELLE STENNUM
BODY HELLEN BODIN
Made in China
Made in China
Made in China