Hull plating fit-up inspection, Z05, 2026-02-13

Document number	INS-Z05-20260213-1
Revision	1
Status	APPROVED
Classification	INTERNAL
Author	Vira Quarrel
Approved by	-
Date	2026-02-13

Inspection type	Hull plating fit-up inspection
Zone	Z05
Date	2026-02-13
Inspector	Vira Quarrel
Number of findings	2

Findings

ID	Finding	Location	Severity	Action	Due
F-01	Plate misalignment at seam	Deck 45, frame 23	Critical	Re-shim and re-torque the seam.	2026-03-15
F-02	Weld porosity	Deck 43, frame 347	Minor	Grind out and re-weld; repeat inspection.	2026-02-20

Assessment

1 critical findings; non-conformance reports raised.