Thermal vacuum test report: Operations display wall (SN-OC-3776)

Document number	SHV-OC-TR-0002
Revision	1
Status	APPROVED
Classification	INTERNAL
Author	Ferris Ardent
Approved by	Hale Voren
Date	2024-10-14

1. Item under test

Component	Operations display wall (OC-ODW)
Serial number	SN-OC-3776
Specification	SHV-OC-SPEC-0103 Rev C
Procedure	TP-OC-ODW-08

2. Test set-up

The test was performed on 2024-10-14 at the Eadu campus test laboratory. Test engineer: Ferris Ardent. Witness: Hale Voren.

- Six-axis shaker table
- Containment field analyser
- Thermal vacuum chamber TV-3

3. Results

Requirement	Parameter	Required	Tolerance	Measured	Result
OC-ODW-R01	Display panels	75 ea	±5%	75 ea	PASS

4. Anomalies

None.

5. Conclusion

Overall result: PASS. The unit is released for integration.