Qualification test report: Tram track segment (SN-TR-4164)

Document number	SHV-TR-TR-0014
Revision	1
Status	APPROVED
Classification	INTERNAL
Author	Zeva Vexley
Approved by	Esme Hesk
Date	2026-09-21

1. Item under test

Component	Tram track segment (TR-TRK)
Serial number	SN-TR-4164
Specification	SHV-TR-SPEC-0104 Rev D
Procedure	TP-TR-TRK-11

2. Test set-up

The test was performed on 2026-09-21 at the Eadu campus test laboratory. Test engineer: Zeva Vexley. Witness: Esme Hesk.

- Six-axis shaker table
- Data acquisition rack DAQ-12
- Precision metrology arm

3. Results

Requirement	Parameter	Required	Tolerance	Measured	Result
TR-TRK-R01	Segment length	68 m	±5%	65.5 m	PASS
TR-TRK-R02	Segment count	7,799 ea	±2.5%	8,085 ea	FAIL

4. Anomalies

Out-of-tolerance result recorded; non-conformance report NCR-2026-0021 raised.

5. Conclusion

Overall result: FAIL. The unit is held pending disposition of the non-conformance.