Endurance test report: Heat exchanger stack (SN-TX-6691)

Document number	SHV-TX-TR-0009
Revision	1
Status	APPROVED
Classification	INTERNAL
Author	Fenna Winter
Approved by	Soren Kessel
Date	2024-03-27

1. Item under test

Component	Heat exchanger stack (TX-HXS)
Serial number	SN-TX-6691
Specification	SHV-TX-SPEC-0101 Rev C
Procedure	TP-TX-HXS-07

2. Test set-up

The test was performed on 2024-03-27 at the Station Integration Test Facility, Zone Z05. Test engineer: Fenna Winter. Witness: Soren Kessel.

- Precision metrology arm
- Thermal vacuum chamber TV-3
- Calibrated field probe set

3. Results

Requirement	Parameter	Required	Tolerance	Measured	Result
TX-HXS-R01	Rejection capacity	0.66 PW	±5%	0.674 PW	PASS
TX-HXS-R02	Stack count	20 ea	±2%	20 ea	PASS

4. Anomalies

None.

5. Conclusion

Overall result: PASS. The unit is released for integration.