

Photo Sheet

Benson Restoration & Construction, Inc.

Lic. #543921

9027 Canoga Ave., Unit D


Canoga Park, Calif., 91340

818-888-7701 * Fax; 818-316-0671

Insured: MACKEY, TERESA

Claim #: 010929933

Policy #: CHO026922328



address ID

Date Taken: 11/1/2012

Taken By: Mike Benson



Front exterior

Date Taken: 11/1/2012

Taken By: Mike Benson

Photo Sheet

Benson Restoration & Construction, Inc.

Lic. #543921

9027 Canoga Ave., Unit D

Canoga Park, Calif., 91340

818-888-7701 * Fax; 818-316-0671

Insured: **MACKEY, TERESA**

Claim #: **010929933**

Policy #: **CHO026922328**



garage

Date Taken: 11/1/2012

Taken By: Mike Benson



tree limb

Date Taken: 11/1/2012

Taken By: Mike Benson

Photo Sheet

Benson Restoration & Construction, Inc.

Lic. #543921

9027 Canoga Ave., Unit D

Canoga Park, Calif., 91340

818-888-7701 * Fax; 818-316-0671

Insured: **MACKEY, TERESA**

Claim #: **010929933**

Policy #: **CHO026922328**



tree that broke

Date Taken: 11/1/2012

Taken By: Mike Benson



garage / office

Date Taken: 11/1/2012

Taken By: Mike Benson

Photo Sheet

Benson Restoration & Construction, Inc.

Lic. #543921

9027 Canoga Ave., Unit D

Canoga Park, Calif., 91340

818-888-7701 * Fax; 818-316-0671

Insured: MACKEY, TERESA

Claim #: 010929933

Policy #: CHO026922328



damaged fascia

Date Taken: 11/1/2012

Taken By: Mike Benson



broken rafters

Date Taken: 11/1/2012

Taken By: Mike Benson

Photo Sheet

Benson Restoration & Construction, Inc.

Lic. #543921

9027 Canoga Ave., Unit D

Canoga Park, Calif., 91340

818-888-7701 * Fax; 818-316-0671

Insured: MACKEY, TERESA

Claim #: 010929933

Policy #: CHO026922328



broken rafters

Date Taken: 11/1/2012

Taken By: Mike Benson



broken overhang

Date Taken: 11/1/2012

Taken By: Mike Benson

Photo Sheet

Benson Restoration & Construction, Inc.

Lic. #543921

9027 Canoga Ave., Unit D

Canoga Park, Calif., 91340

818-888-7701 * Fax; 818-316-0671

Insured: **MACKEY, TERESA**

Claim #: **010929933**

Policy #: **CHO026922328**



roof

Date Taken: 11/1/2012

Taken By: Mike Benson



roof

Date Taken: 11/1/2012

Taken By: Mike Benson

Photo Sheet

Benson Restoration & Construction, Inc.

Lic. #543921

9027 Canoga Ave., Unit D

Canoga Park, Calif., 91340

818-888-7701 * Fax; 818-316-0671

Insured: **MACKEY, TERESA**

Claim #: **010929933**

Policy #: **CHO026922328**



roof

Date Taken: 11/1/2012

Taken By: Mike Benson



roof

Date Taken: 11/1/2012

Taken By: Mike Benson

Photo Sheet

Benson Restoration & Construction, Inc.

Lic. #543921

9027 Canoga Ave., Unit D

Canoga Park, Calif., 91340

818-888-7701 * Fax; 818-316-0671

Insured: MACKEY, TERESA

Claim #: 010929933

Policy #: CHO026922328



damaged roof

Date Taken: 11/1/2012

Taken By: Mike Benson



garage / office

Date Taken: 11/1/2012

Taken By: Mike Benson

Photo Sheet

Benson Restoration & Construction, Inc.

Lic. #543921

9027 Canoga Ave., Unit D

Canoga Park, Calif., 91340

818-888-7701 * Fax; 818-316-0671

Insured: **MACKEY, TERESA**

Claim #: **010929933**

Policy #: **CHO026922328**



garage / office

Date Taken: 11/1/2012

Taken By: Mike Benson



garage / office

Date Taken: 11/1/2012

Taken By: Mike Benson