InspectionWale Rebranded from Whizzcheck Vehicle Inspection Report

Inspection ID: INS-1760171948

Date: 11 Oct 2025

Vehicle Registration Details

Vahiala Number	MUOAKDOOFF
Vehicle Number	MH04KD2255
Make / Model	Maruti Brezza
Variant	VDi
Chassis Number	MA3NYF81SKD535417
Engine Number	D13A-5818272
Manufacture Year	2019
Registration Date	2019-09-19
Fuel Type	Diesel
Color	Pearl White
Odometer Reading	45320 km
Number of Owners	2

Current Owner Details

Owner Name	Akshada Sondulkar
Contact Number	9876543210
Email Address	akshada@example.com
Inspection Location	Byculla, Mumbai

Inspection Details

Inspector Name	Prasad Kumar
Inspection Date	11 Oct 2025

Key Highlights

Exterior: No major dents. Paint in good condition. Minor scratches on rear bumper.

Interior: Dashboard clean. All controls working. Seats show normal wear. **Engine:** Engine running smoothly. No oil leaks. Battery in good condition.

Overall Ratings

Interior	★★★★ (4.0/5)
Exterior / Body	★★★★★ (4.5/5)
Engine	★★★★ (4.0/5)
Structure	★★★★★ (5.0/5)
Test Drive	★★★★★ (4.5/5)
Electrical	★★★★ (4.0/5)

Vehicle Photos

РНОТО	РНОТО
Bonnet	Grille
РНОТО	РНОТО
	Bonnet

Dashboard	Seats	Engine Bay
РНОТО	РНОТО	РНОТО