InspectionWale

Professional Vehicle Inspection Services

INSPECTION REPORT

Report ID: INS-1760179836895

Date: 11 Oct 2025 Inspector: Prasad

KEY HIGHLIGHTS

Accident: No | Flood: No | Fire: No

VEHICLE REGISTRATION DETAILS

Registration Number Make / Model Variant
MH46CH6894 TATA Altroz N/A

Chassis Number Engine Number

N/A N/A

Manufacture Year Registration Date Color

2023 N/A Dark Black

Fuel Type Odometer Reading Number of Owners

Petrol 35000 km

Vehicle Document Photos:







Chassis Plate

CURRENT OWNER DETAILS

Owner Name Contact Number **Roshan Kutty** 9321449764

Email Address Location roshr98@gmail.com **Panvel**

OVERALL ASSESSMENT

Overall Condition Good

EXTERIOR / BODY INSPECTION

Exterior Photos:








Bonnet







Wipers











Boot (Closed)

Boot (Open)





Rear Windshield

Roof

INTERIOR INSPECTION

Interior Photos:







Dashboard

Instrument Cluster

Steering Wheel







Front Seats

Rear Seats

AC Control Panel








Music System Gear Lever Interior Roo

ENGINE & MECHANICAL INSPECTION

Engine & Mechanical Photos:







Engine Block



Battery



Radiator



Oil Cap



Belts & Hoses

TIRES & WHEELS INSPECTION

Front LHS

N/A

Rear LHS

N/A

Spare Tire

N/A

Front RHS

N/A

Rear RHS

N/A

Tire & Wheel Photos:



Front Left Tire



Front Right Tire



Rear Left Tire



Rear Right Tire



Spare Tire

TEST DRIVE ASSESSMENT

Test Drive Conducted: Yes

<u>Undercarriage & Structure Photos:</u>







Front Undercarriage

Rear Undercarriage

Front Suspension



Rear Suspension

