

InspectionWale

Rebranded from Whizzcheck Vehicle Inspection Report

Inspection ID:  
INS-1760174344

Date:  
11 Oct 2025

Vehicle Registration Details

Vehicle Number	MH04KD2255	Make / Model	Maruti Brezza
Variant	VDi	Chassis Number	MA3NYF81SKD535417
Engine Number	D13A-5818272	Manufacture Year	2019
Registration Date	2019-09-19	Fuel Type	Diesel
Color	Pearl White	Odometer Reading	45320 km
Number of Owners	2		

Current Owner Details

Owner Name	Akshada Sondulkar	Contact Number	9876543210
Email Address	akshada@example.com	Inspection Location	Byculla, Mumbai

Inspection Details

Inspector Name	Prasad Kumar	Inspection Date	11 Oct 2025
----------------	--------------	-----------------	-------------







Key Highlights

**Exterior:** No major dents. Paint in good condition. Minor scratches on rear bumper.

**Interior:** Dashboard clean. All controls working. Seats show normal wear.

**Engine:** Engine running smoothly. No oil leaks. Battery in good condition.

## Overall Ratings

Interior	 (4.0/5)
Exterior / Body	 (4.5/5)
Engine	 (4.0/5)
Structure	 (5.0/5)
Test Drive	 (4.5/5)
Electrical	 (4.0/5)

## Vehicle Photos

RC Book	Chassis Plate	Odometer
PHOTO	PHOTO	PHOTO

Front Bumper	Bonnet	Grille
PHOTO	PHOTO	PHOTO

Dashboard	Seats	Engine Bay
PHOTO	PHOTO	PHOTO