

## KEY HIGHLIGHTS

Accident: No | Flood: No | Fire: No

## VEHICLE REGISTRATION DETAILS

Registration Number  
**MH46CH6894**

Make / Model  
**TATA Altroz**

Variant  
**N/A**

Chassis Number  
**N/A**

Engine Number  
**654321**

Manufacture Year  
**2023**

Registration Date  
**N/A**


Color  
**Dark edition**

Fuel Type  
**Petrol**


Odometer Reading  
**32000 km**

Number of Owners  
**1**

### Vehicle Document Photos:



RC Book



Chassis Plate

## CURRENT OWNER DETAILS

Owner Name	Contact Number
Roshan Kutty	9321449764
Email Address	Location
roshr98@gmail.com	Panvel


## OVERALL ASSESSMENT

Overall Condition


Good

## EXTERIOR / BODY INSPECTION


Exterior Photos:



Front Bumper




Bonnet




Windshield




Wipers




Left Mirror




Right Mirror




Rear Bumper




Boot (Closed)



Boot (Open)




Rear Windshield




Roof

## INTERIOR INSPECTION


### Interior Photos:




Dashboard




Instrument Cluster




Steering Wheel




Front Seats




Rear Seats




AC Control Panel



Music System




Gear Lever




Interior Roof

## ENGINE & MECHANICAL INSPECTION


Engine & Mechanical Photos:




Engine Bay




Engine Block




Battery



Radiator



Oil Cap



Belts & Hoses

## TIRES & WHEELS INSPECTION

Front LHS  
**N/A**


Front RHS  
**N/A**

Rear LHS  
**N/A**


Rear RHS  
**N/A**

Spare Tire  
**N/A**


### Tire & Wheel Photos:




Front Left Tire




Front Right Tire




Rear Left Tire



Rear Right Tire



Spare Tire




Alloy Wheels


## TEST DRIVE ASSESSMENT

Test Drive Conducted: Yes


Undercarriage & Structure Photos:




Front Undercarriage



Rear Undercarriage



Front Suspension



Rear Suspension



























