

InspectionWale

Rebranded from Whizzcheck Vehicle Inspection Report

Inspection ID:
INS-1760170133

Date:
11 Oct 2025

Vehicle Registration Details

Vehicle Number	MH04KD2255
Make / Model	Maruti Brezza
Variant	VDi
Chassis Number	MA3NYF81SKD535417
Engine Number	D13A-5818272
Manufacture Year	2019
Registration Date	2019-09-19
Fuel Type	Diesel
Color	Pearl White
Odometer Reading	45320 km
Number of Owners	2

Current Owner Details

Owner Name	Akshada Sondulkar
Contact Number	9876543210
Email Address	akshada@example.com
Inspection Location	Byculla, Mumbai

Inspection Details

Inspector Name	Prasad Kumar
Inspection Date	11 Oct 2025

Key Highlights


Exterior: No major dents. Paint in good condition. Minor scratches on rear bumper.
Interior: Dashboard clean. All controls working. Seats show normal wear.
Engine: Engine running smoothly. No oil leaks. Battery in good condition.

Overall Ratings

Interior	★★★★■ (4.0/5)
----------	---------------

Exterior / Body	★★★★★ (4.5/5)
Engine	★★★★■ (4.0/5)
Structure	★★★★★ (5.0/5)
Test Drive	★★★★★ (4.5/5)
Electrical	★★★★■ (4.0/5)


Vehicle Photos



RC Book

Chassis Plate


Odometer Reading



Front Bumper

Bonnet

Front Grille



Windshield

Headlights

Dashboard