InspectionWale/ehicle Inspection Report

Rebranded from Whizzcheck

Inspection ID: INS-2025-001234

Date:

11 Oct 2025

Ø=ÜË Vehicle Registration Details

Vehicle NumberMH04KD2255Manufacturing Date2019-04-01Chassis NumberMA3NYF81SKD535417 Insurance Validity2025-09-29Engine NumberD13A-5818272Registration Date2019-09-19

Make / Model Maruti Brezza Variant VDi

Fuel TypeDieselColorPearl WhiteNumber of Owners2Odometer Reading45,320 km

Ø=Üd Current Owner Details

Owner Name Akshada Sondulkar

CNG Validity 2025-09-29

CNG Fitment Company fitted

RC Type Private

Hypothecation No

Ø=Ý Inspection Details

Inspected ByPrasad KumarLocationByculla, Mumbai

+P Key Highlights

Accidental: No major accident detected

' Flood Damage: No flood damage signs

Ø=ÜÊ Overall Ratings

Interior: 4/5 - Good condition with minor wear

Exterior Body: 4.5/5 - Excellent body condition

Engine: 4/5 - Running smoothly, no leaks

Structure Ratings: 5/5 - No structural damage


Test Drive: 4.5/5 - Excellent performance

Electrical: 4/5 - All systems working

Ø=ÜÄ Vehicle Documents

PHOTO

RC Book



PHOTO

Odometer Reading

Ø=Þ— Exterior - Front Section

Front Bumper Condition Good

Repainted No


Paint Depth 125 microns

Bonnet Condition Excellent


Repainted No


Paint Depth 130 microns

PHOTO
Front Bumper











Thank You!

This report has been prepared by certified vehicle inspectors at InspectionWale.

Report is valid for 2 days or 20 km, whichever is earlier.

For any queries, please contact us at hello@inspectionwale.com