

	A	B	F	G	H	I
1	VF5NP					
2	Scoring --> 1 to 8		28.05.2026			
3	8 = Excellent or Outstanding experience/comfort		Bùi Việt Anh			
4	7 = Good level of comfort/satisfaction		VNese			
5	6 = Acceptable but still some improvements could be added to improve comfort		21			
6	5 = Not OK. In many customers will be unhappy with comfort experience		M			
7	4 and below rating are Not OK --> need corrections as brand image would have		188			
8			81			
9			3 years			
10						
11	Level 1					
12	1. DRIVER POSITION	Assessment Point	Score	Comments	Average score	
13	VISIBILITY - DRIVER POSITION	FRONT VISIBILITY	7		7	
14		SIDE VISIBILITY	7		7	
15		ORVM SIZE, POSITION & VISIBILITY	7		7	
16		IRVM SIZE, POSITION & VISIBILITY	7		7	
17		A-PILLAR HINDRANCE (STATIC)	7		6.5	
18		B-PILLAR HINDRANCE (STATIC)	7		7	
19	ROOMINESS - 1st ROW - DRIVER POSITION	HEAD ROOM	7		7.5	
20		SHOULDER ROOM	7		7.5	
21		ELBOW ROOM	5	Elbow collides with armrest while turn	5	
22		HIP ROOM	7		7.5	
23		KNEE ROOM	7		6.5	
24		LEG ROOM	7		7	
25		HINDRANCE BY ENVIRONMENT PARTS	5	Steering - too big, thick.	6	
26		PERCEIVED ROOMINESS	7		7	
27		CONTROL POSITION	4	Struggle to reach both stalks - too far away	5.5	
28		CONTROL LENGTH/WIDTH/ANGLES	7		7	
29		DRIVE SELECTOR SWITCH	7		7	
30		BOOT/HOOD RELEASE	7		6	

	A	B	F	G	H	I
31	PRIMARY CONTROLS - DRIVER POSITION	INTERIOR DOOR OPENING LEVER	4	gets stuck	5	
32		EXTERIOR DOOR OPENING LEVER	7		7	
33		ORVM ADJUSTMENT SWITCH	5	want physical adjustment	5.5	
34		PARKING BRAKE			8	
35		WINDOW ADJUSTMENT SWITCH	5	delay + no auto	6	
36		CABIN LIGHT	8	surprisingly bright	7.5	
37		SUN VISOR	7		6.5	
38		EASE OF UNDERSTANDING SYMBOLS	7		6.5	
39		LOGIC OF CONTROLS/SWITCHE S/LEVERS	7		7	
40		OPERATING FORCE EASINESS	7		7.5	
41	PEDALS - DRIVER POSITION	POSITION & ANGLE OF ACCELERATOR PEDAL	7		7	
42		POSITION & ANGLE OF BRAKE PEDAL	7		7	
43		POSITION & ANGLE OF REST PEDAL	7		7	
44		SPACING BETWEEN PEDALS	7		6.5	
45		LIFT OFF HEIGHT & ANGLE	7		7	
46		PEDAL TRAVEL	7		7	
47		WIDTH/SIZE OF PEDALS	7		7	
48		FOOT CLEARANCE WITH SURROUNDING PARTS	7		7	
49		OPERATING FORCE EASINESS	7		7	
50		EASINESS OF PEDAL OPERATION	7		7	
51		LEG/THIGH CLEARANCE WHILE OPERATING	7		6	
52		POSITION OF STEERING WHEEL	6	want bigger range of height adjustm.	6	
53		SIZE OF SW	5	too big	5.5	
54		ANGULAR ADJUSTMENT OF SW	6	want bigger range of height adjustm.	6.5	

	A	B	F	G	H	I
55	STEERING WHEEL - DRIVER POSITION	REACH ADJUSTMENT OF SW	7		6.333333	
56		SW/SHROUD TO THIGH/KNEE CLEARANCE	7		6	
57		ADJUSTMENT LEVER ACCESSIBILITY	7		7	
58		HORN PAD ACCESSIBILITY	8	improvement compared with VF8 NP	7	
59		SWITCHES POSITION, SIZE & EASE OF USE	7		6	
60		OPERATING FORCE EASINESS OF SWITCHES	7		7	
61		OPERATING EASE TURN-TURN (STATIC)	6	Due to large SW, my hand goes too high	6.5	
62		ARM & HAND CLEARANCE	7		7	
63		STALK POSITION & REACHABILITY	4	Too far away	5.5	
64	SEATS - DRIVER POSITION	POSITION OF SEATS	6		5.5	
65		SIZE OF SEATS	7		7	
66		REACH ADJUSTMENT OF SEATS	6	no lever available (no recline adjustment (no lever on this vehicle))	6	
67		HEIGHT ADJUSTMENT OF SEATS	7		7.333333	
68		ANGULAR ADJUSTMENTS OF SEATS	NA	no lever available	#DIV/0!	
69		ADJUSTMENT LEVERS ACCESSIBILITY	6	no lever available (no recline adjustment (no lever on this vehicle))	6.5	
70		CUSHION COMFORT	5	upper back is protruding	4.5	
71		THIGH COMFORT	5	need more even pressure distrib.	4.5	
72		BOLSTER COMFORT	8	decent support for A-segment model	7.5	
73		BACK COMFORT	5	upper back is protruding	4.5	
74		FIRMNESS/SOFTNESS	5	want softer	5	

	A	B	F	G	H	I
75		OVERALL POSTURE	5	improve at seat back + headrest	5	
76		REACHABILITY OF SEAT BELTS	7		7	
77		REACHABILITY OF BUCKLE	7		7	
78		OPERATING FORCE FOR BELTS	7		7	
79		OPERATING FORCE OF BUCKLE	7		7	
80		BELT COMFORT OVER SHOULDER/NECK	7		7	
81	INGRESS/EGRESS - DRIVER POSITION	Head Clearance/Hindrance	5	need to bend down significantly to enter		
82		Hip/Lower Body Clearance	7			
83		Leg Clearance/Hindrance	6			
84		Overall Postural Comfort	7			
85	ACCESSORIES - DRIVER POSITION	SUN VISOR MIRROR	NA		#DIV/0!	
86		GRAB HANDLE	NA	sunglasses holder	N/A	
87		GLOVE BOX	7		N/A	
88		BOTTLE HOLDER	7		6.5	
89		ARMREST	7		6.5	
90		USB PORTS	7		6.5	
91	DRIVER INFO SYS - DRIVER POSITION	OPERATING FORCE EASINESS	7		6.5	
92		POSITION, SIZE & REACHABILITY OF DIS	7		7	
93		LOGIC & VISUAL CLARITY OF SYMBOLS	7		7	
94	2. 1st ROW PASSENGER POSITION					
95	VISIBILITY - 1st ROW Passenger POSITION	FRONT VISIBILITY	7		7	
96		SIDE VISIBILITY	7		7	
97		OVERALL PERCEIVED ROOMINESS	7		7.5	
98	ROOMINESS - 1st ROW Passenger POSITION	HEAD ROOM	7		7.5	
99		SHOULDER ROOM	7		7.5	
100		ELBOW ROOM	7		7	
101		HIP ROOM	7		7.5	
102		KNEE ROOM	7		6.5	
103		LEG ROOM	6	wheel arch hinders	5.5	

	A	B	F	G	H	I
104		HINDRANCE BY ENVIRONMENT PARTS	5	knee hits glove box	5.5	
105		PERCEIVED ROOMINESS	7		6	
106	SEATS & BELTS - 1st ROW Passenger POSITION	POSITION OF SEATS	7		7	
107		SIZE OF SEATS	7		7	
108		REACH ADJUSTMENT OF SEATS	7		7	
109		HEIGHT ADJUSTMENT OF SEATS	NA		N/A	
110		ANGULAR ADJUSTMENTS OF SEATS	7		N/A	
111		ADJUSTMENT LEVERS ACCESSIBILITY	7		7	
112		CUSHION COMFORT	5	want softer	5.5	
113		THIGH COMFORT	5	pressure distrib.	6	
114		BOLSTER COMFORT	7		7.5	
115		BACK COMFORT	5	same as Driver position	5.5	
116		FIRMNESS/SOFTNESS	6		6	
117		OVERALL POSTURE	5	same as Driver position	5.5	
118		REACHABILITY OF SEAT BELTS	7		7.5	
119		REACHABILITY OF BUCKLE	7		7	
120		OPERATING FORCE FOR BELTS	7		7	
121		OPERATING FORCE OF BUCKLE	7		7	
122		BELT COMFORT OVER SHOULDER/NECK	7		7	
123	INGRESS/EGRESS - 1st Row	HEAD CLEARANCE/HINDRANCE	6			
124		HIP/LOWER BODY CLEARANCE	6			
125		LEG CLEARANCE/HINDRANCE	7			
126		OVERALL POSTURAL COMFORT	6			
127		SUN VISOR MIRROR - POSITION & SIZE	7		6.5	

	A	B	F	G	H	I
128	ACCESSORIES - 1st ROW Passenger POSITION	GRAB HANDLE - POSITION, SIZE & REACHABILITY	7		7.5	
129		GLOVE BOX - SIZE, REACHABILITY AND ACCESS	7		6.5	
130		BOTTLE HOLDER - POSITION, SIZE & REACHABILITY	7		7	
131		ARMREST - POSITION, SIZE & REACHABILITY	7		7	
132		USB PORTS - POSITION, REACHABILITY & VISIBILITY	7		7	
133		OPERATING FORCE EASINESS OF CONTROLS	7		7	
134		CENTER CONSOLE STORAGE	7		7	
135		PHONE HOLDER	7		6.5	
136		DOOR TRIM STORAGE	7		6.5	
137		12V PLUG ACCESS	7		7	
138	3. 2nd ROW PASSENGER POSITION					
139	ROOMINESS - 2nd ROW Passenger POSITION	HEAD ROOM	7		6.5	
140		SHOULDER ROOM	7		6.5	
141		ELBOW ROOM	7		6.5	
142		HIP ROOM	7		7.5	
143		KNEE ROOM	7		7.5	
144		LEG ROOM	6	can't fully put my feet under seat in front	6.5	
145		HINDRANCE BY ENVIRONMENT PARTS	7		7	
146		PERCEIVED ROOMINESS	7		6.5	
147	INGRESS/EGRESS - 2nd ROW Passenger POSITION	HEAD CLEARANCE/HINDRANCE	6	forehead/back head - touching even when bending down	5.5	
148		HIP/LOWER BODY CLEARANCE	7		6.5	
149		LEG CLEARANCE/HINDRANCE	7		5.5	

	A	B	F	G	H	I
150		OVERALL POSTURAL COMFORT	6		6.5	
151		POSITION OF SEATS	7		7.5	
152		SIZE OF SEATS	7		7	
153		CUSHION COMFORT	7		6	
154		THIGH COMFORT	6		6.5	
155		BOLSTER COMFORT	7		6.5	
156		BACK COMFORT	7		6.5	
157		FIRMNESS/SOFTNESS	7		7	
158		OVERALL POSTURE	6	will soon suffer on long rides - due to leg resting	5	
159	SEATS & BELTS - 2nd ROW Passenger POSITION	POSITION OF SEAT BELTS	7		7	
160		POSITION OF BUCKLES	7		7	
161		REACHABILITY OF SEAT BELTS	7		7	
162		REACHABILITY OF BUCKLE	6	will struggle to look for buckle in the dark	6.5	
163		OPERATING FORCE FOR BELTS	7		7	
164		OPERATING FORCE OF BUCKLE	7		7	
165		BELT COMFORT OVER SHOULDER/NECK	7		7	
166		INTERIOR DOOR OPENING LEVER	5	cannot open left door from inside + broken plastic	6	
167		EXTERIOR DOOR OPENING LEVER	7		7	
168		WINDOW ADJUSTMENT SWITCH	5	delay + no auto	6	
169		CABIN LIGHT - POSITION, SIZE & REACHABILITY	7		N/A	
170		GRAB HANDLE - POSITION, SIZE & REACHABILITY	7		7	
171	ACCESSORIES - 2nd Row Passenger POSITION	BOTTLE HOLDER - POSITION, SIZE & REACHABILITY	5	rough plastic + hardly fits my 700ml bottle (check photo)Center armrest = NA. door armrest = fine.	5	

	A	B	F	G	H	I
172		ARMREST - POSITION, SIZE & REACHABILITY	7		7	
173		USB PORTS - POSITION & VISIBILITY	NA		#DIV/0!	
174		EASE OF UNDERSTANDING OF SYMBOLS	7		7	
175		LOGIC OF CONTROLS/SWITCHES/LEVERS	5	window logic: delay + no auto	6	
176		OPERATING FORCE EASINESS	7		6	
177		SEAT POCKET - POSITION, SIZE & USABILITY	8		7.666667	
178	5. Vehicle check					
179	CARGO & STOWAGE	TRUNK DOOR HANDLE/SWITCH	7		7	
180		TRUNK DOOR ACCESSIBILITY WHEN OPEN/CLOSE	6	Trunk open/close effort: 4. Very much force to close trunk + Check gas strut adjust. + Women would not be able to operate effortlessly	3.666667	
181		LUGGAGE ROOM SIZE	7		7	
182		LUGGAGE LIFT-IN HEIGHT	8		7	
183		TRUNK OPENING AREA SIZE	7		7	
184		TRUNK LIGHT	4	Required to install	4	
185		SPARE WHEEL ACCESSIBILITY	NA	no spare wheel + can't open	#DIV/0!	
186		SPARE WHEEL - WHEELWELL AREA SIZE	NA		#DIV/0!	
187		TOOLS ACCESSIBILITY	NA		#DIV/0!	
188		TOOLS ORGANIZATION	NA		#DIV/0!	
189		12V PLUG ACCESS	NA		N/A	

	A	B	F	G	H	I
190	FRUNK USABILITY	HOOD STAY ROD POSITION	4	No icon indicating to which hole should put a rod / the holes do not fit the rod smoothly - risk of metal crack	5	
191		CLEARANCE WITH HEAD & HOOD	7		7.666667	
192		FRUNK - POSITION, SIZE & USABILITY	NA		N/A	