

Residential Inspection Summary

Synthetic home inspection attachment

Section	Summary
Property	San Diego area single-family residence
Roof	Serviceable, monitor minor flashing wear.
Electrical	Panel labeled; recommend GFCI check in garage.
Plumbing	No active leaks observed during walkthrough.
Follow-Up	Request seller clarification on HVAC service history.

This synthetic report supports personal-noise email threads in the workshop mailbox.