

MANGALORE REFINERY AND PETROCHEMICALS LIMITED (MRPL)  
EQUIPMENT INSPECTION REPORT — CDU UNIT 1  
Equipment ID: MRPL-PUMP-101-B  
Equipment Description: Crude Feed Centrifugal Pump  
Inspection Date: 2026-09-02

OBSERVATIONS:

- Drive-End Bearing Housing Temperature: 82°C (Warning threshold: 75°C).
- Mechanical Seal Zone: Active seal flush oil leakage observed at 15 drops/min.
- Overall Vibration Level: 4.8 mm/s RMS (SOP limit: 4.5 mm/s).
- Acoustic Inspection: Audible high-frequency bearing clicking noise.

INSPECTOR RECOMMENDATION:

Urgent maintenance inspection required to prevent bearing seizure and unplanned shutdown.