AAK1758104116

MOTOR VEHICLE VALUATION & INSPECTION

CERTIFICATE

PRE-INSURANCE

This is to certify that the vehicle

Registration Number :	**KDT 466Q**
Vehicle Make :	**SUBARU**
Vehicle Model Number :	**Forester**
Chassis Number :	**CHASSISDAN10078-OP**
Year of Manufacture :	**2017**

Has been inspected and assessed by AA of Kenya and valued at

KES 4,168,562.00

(FOUR MILLION ONE HUNDRED SIXTY EIGHT THOUSAND FIVE HUNDRED SIXTY TWO ONLY)

A detailed report is attached.

Valuation & Inspection Manager

AA KENYA P.O. Box 40087 - 00100. NAIROBI

Valuation & Inspection Officer

Date : 18/09/2025

INSURED DETAILS

Insured	:	Test By Dan
Insured Tel	:	+254782767684
Email	:	danwamuyu06@gmail.com

VEHICLE DETAILS

Reg. No	:	KDT 466Q
Vehicle Make	:	SUBARU
Vehicle Model Number	:	Forester
Colour	:	Purple
YOM	:	2017
Chassis No	:	CHASSISDAN10078-OP

INSURER DETAILS

No insurance details available

Valuation & Inspection Manager

AA KENYA
P.O. Box 40087 - 00100. NAIROBI

Valuation & Inspection Officer

Date : 18/09/2025

VALUATION ASSESSMENT COMMENTS

Body	:	CHASIS HAS BEEN WELDED
Engine	:	FAN IS FAULTY
Transmission	:	GOOD CONDITION
Electrical	:	GOOD CONDITION
Suspension	:	CV JOINTS ARE WORN OUT
Steering	:	GOOD CONDITION
Braking	:	GOOD CONDITION
Tyres	:	5 OF GOOD THREAD DEPTH

Extras:

POWER WINDOWS, POWER MIRRORS, POWER STEERING, CDL, ARMREST, CUPHOLDERS, AC, ABS, SMART IGNITION

Remarks

EX JAPAN.
CHASIS IS WELDED.

Examiner's Opinion:

KES 4,168,562.00 (FOUR MILLION ONE HUNDRED SIXTY EIGHT THOUSAND FIVE HUNDRED SIXTY TWO)

Valuation & Inspection Manager


AA KENYA
P.O. Box 40087 - 00100. NAIROBI

Valuation & Inspection Officer


Date : 18/09/2025

INSPECTION IMAGES


LOGBOOK




ID



KRA PIN



VIN PLATE




Valuation & Inspection Manager

Valuation & Inspection Officer


Date : 18/09/2025

INSPECTION IMAGES (CONTINUED)


REAR RIGHT TYRE




FRONT RIGHT TYRE



REAR LEFT TYRE



FRONT LEFT TYRE




Valuation & Inspection Manager

Valuation & Inspection Officer


Date : 18/09/2025

INSPECTION IMAGES (CONTINUED)

ENGINE



INSURANCE STICKER



Valuation & Inspection Manager

Valuation & Inspection Officer

Date : 18/09/2025

Terms & Conditions

The examiners take every care & precaution during inspections but the AA cannot accept responsibility for claims arising as a result of latent defects or matters of opinion

The AA reserves the right to decline to examine or to report on any vehicle not of standard production or one which has not been in regular road use.

The examination to which this report refers is external only and does not involve dismantling or disturbing any structure, assembly, component or internal mechanism.

Only limited road test is undertaken.

Vehicles over 5 years and those that have been subjected to abnormal use may have serious defects which may not be detected by external examination. The AA will not be held responsible for liability arising out of this.

No indication can be given of the availability of the spare parts for the particular make or model of a vehicle.

Parts that are excessively contaminated by oil or dirt may not be properly examined.

The assessed value given after a brief examination and road test is consistent with the age and condition of the said vehicle. However, it must be emphasized that it bears no relationship with any agreement between buyer and seller which is entirely dependent on willingness of the two parties to a greater or lesser degree.

Where it is stated in the inspection report that some information was supplied by AA a third party, the AA Kenya will not be held responsible for the reliability of the information, if found to be incorrect.

Re-examination after repairs will be carried out at a fee.

The assessed value is based on the date of first registration and the odometer reading being genuine.

Valuation & Inspection Manager

AA KENYA
P.O. Box 40087 - 00100. NAIROBI

Valuation & Inspection Officer

Date : 18/09/2025