1084125182/101010/FM/6500

MOTOR VEHICLE VALUATION & INSPECTION

CERTIFICATE

FULL MECHANICAL VEHICLE INSPECTION

This is to certify that the vehicle

Registration Number : KCW078W

Vehicle Make : TOYOTA RUSH

Vehicle Model Number : F800E

Chassis Number : MHKE8FB200K001967

Year of Manufacture : 2019

AUTOMOBILE ASSOCIATION OF KENYA
GATE HOUSE
2ND FLOOR, RM 215
TEL: 051-2213215
051-221 7293
0729561719
NAKURU BRANCH

Has been inspected and assessed by AA of Kenya and valued at

KES. 1,890,000 (Kenya Shillings ONE MILLION EIGHT HUNDRED NINETY THOUSAND ONLY)

A detailed report is attached.

Valuation & Inspection Manager

Valuation & Inspection Officer

Date : 15/08/2025

1084125182/101010/FM/6500

MOTOR VEHICLE VALUATION & INSPECTION

FULL MECHANICAL VEHICLE INSPECTION

CLIENT DETAILS

Client Name	: TOTAL ENERGIES PLC
Telephone No	: +254700000000
Address	: -

VEHICLE DETAILS

Reg. No	: KCW078W
Vehicle Make	: TOYOTA RUSH
Vehicle Model Number	: F800E (1490 CC)
Type	: STATION WAGON
Transmission	: AUTO
Engine Type	: 4CYL
Colour	: GREY
Odometer	: 134928 KM
YOM	: 2019
Date Of 1st Reg	: 2021-08-15T10:29:00+03:00
Chassis No	: MHKE8FB200K001967
Engine No	: 2NRF891751
Ex-Country Reg	: LOCAL

AUTOMOBILE ASSOCIATION OF KENYA
GATE HOUSE
2ND FLOOR, RM 218
TEL: 051-2213215
051-2217[illegible]
0729561719
NAKURU BRANCH

Examiner's Opinion (Kshs) : 1,890,000 (Kenya Shillings ONE MILLION EIGHT HUNDRED NINETY THOUSAND ONLY)

Date : 15/08/2025

Valuation & Inspection Manager

Valuation & Inspection Officer

Front



Back



Other



Other



Date : 15/08/2025

Valuation & Inspection Manager

Valuation & Inspection Officer

Terms & Conditions

The examiners take every care & precaution during inspections but the AA cannot accept responsibility for claims arising as a result of latent defects or matters of opinion

The AA reserves the right to decline to examine or to report for any vehicle not of standard production or one which has not been in regular road use.

The examination to which this report refers is external only and does not involve dismantling or disturbing any Parts that are excessively contaminated by oil or dirt may not be properly examined.

The assessed value given after a brief examination and road test is consistent with the age and condition of the said vehicle. However, it must beemphasized that it bears no relationship with any agreement between buyer and seller which is entirely dependent on willingness of the two parties to a greater or lesser degree.

KCW078W

A: BODY WORK		CRACKED	WORN AND/OR DETERIORATED	DENTED AND /OR DAMAGED	LOOSE AND/OR MISALIGNED	BADLY CORRODED	SLIGHTLY CORRODED	OIL AND/OR DIRT FOULED	NOT WATERTIGHT	YES	SATISFACTORY	ACCEPTABLE FOR AGE AND MILEAGE RECORDED	BELOW AVERAGE FOR AGE & MILEAGE RECORDED	NO	REQUIRES ATTENTION IN THE NEAR FUTURE	REQUIRES IMMEDIATE ATTENTION	DANGEROUS AND /OR UNROADWORTHY	NOT CHECKED
1.DOORS	LF											✓						
	RF											✓						
	LR											✓						
	RR											✓						
2.DOOR LOCKS	LF											✓						
	RF											✓						
	LR											✓						
	RR											✓						
3.WINDOWS	LF											✓						
	RF											✓						
	LR											✓						
	RR											✓						
4.WINDOW WINDERS	LF											✓						
	RF											✓						
	LR											✓						
	RR											✓						
5.QUARTER LIGHT GLASS	~~LF~~																	
	~~RF~~																	
	LR										✓							
	RR																	
6.WINGS OR WING AREA	LF											✓						
	RF											✓						
	LR											✓						
	RR											✓						
7.~~QUARTER PANELS~~	~~LF~~																	
	~~RF~~																	
	~~LR~~																	
	~~RR~~																	
8.BOOT OR TAILGATE LOCK												✓						
9.BOOT INTERIOR												✓						
10.BONNET PANEL												✓						
11.BONNET LOCK												✓						
12.RADIATOR GRILLE												✓						
13.ROOF												✓						
14.WINDSCREEN												✓						
15.REAR WINDOW												✓						
16.BODY SILLS	F											✓						
	R											✓						
17.JACKING POINTS	L											✓						
	R											✓						

AUTOMOBILE ASSOCIATION OF NAKURU BRANCH
GATE HOUSE
2ND FLOOR, RM 218
TEL: 051-2213216
051-22[illegible]7293
0729561719

COMMENTS

OK

A: BODY WORK (continued)		WORN AND/OR DETERIORATED	DENTED AND /OR DAMAGED	LOOSE AND/OR MISALIGNED	BADLY CORRODED	SLIGHTLY CORRODED	OIL AND/OR DIRT FOULED	NOT WATERTIGHT	YES	SATISFACTORY	ACCEPTABLE FOR AGE AND MILEAGE RECORDED	BELOW AVERAGE FOR AGE & MILEAGE RECORDED	NO	REQUIRES ATTENTION IN THE NEAR FUTURE	REQUIRES IMMEDIATE ATTENTION	DANGEROUS AND /OR UNROADWORTHY	NOT CHECKED
17. EXTERNAL MIRRORS	L									✓							
	R									✓							
18. WING & BOOT MIRROR ~~F~~ ~~R~~																	
19. BUMBPERS	FRONT										✓						
	REAR										✓						
20. BUMBER VALANCE	F										✓						
	REAR										✓						
21. SEATS	FRONT										✓						
	~~CENTER~~																
	REAR										✓						
22.BODY KIT AND PA~~RKING SENSORS~~	F										✓						
	R										✓						
23. UPHOLSTERY										✓							
24. AIR BAGS										✓							
25. ROOF LINING										✓							
26. UNDERLAY										✓							
27. FLOOR										✓							
28. INTERNAL MIRRORS										✓							
29.SUN ~~ROOFS / PANORAMIC ROOF~~										✓							
30.WOOD WORK	INT										✓						
	~~EXT~~																
31..PAINT WORK:	LUSTRE										✓						
	~~COLOUR VARIATION~~																
	~~REPAIR MATCHING~~																
32. IS THERE EVIDENCE OF ACCIDENT DAMAGE?													✓				
33. IS DAMAGE REPAIR WORK SATISFACTORY?																	

COMMENTS ON BODY WORK

General body condition of the subject vehicle was found to be good

B: WHEELS NOTE WHEEL BALANCE IS NOT CHECKED		WORN AND/OR DETERIORATED	DENTED AND/OR DAMAGED	LOOSE AND/OR MISALIGNED	SLIGHTLY CORRODED	BADLY CORRODED	OIL AND/OR DIRT FOULED	NOT WATERTIGHT	YES	SATISFACTORY	ACCEPTABLE FOR AGE AND MILLEAGE RECORDED	BELOW AVERAGE FOR AGE & MILEAGE RECORDED	NO	REQUIRES ATTENTION IN THE NEAR FUTURE	REQUIRES IMMEDIATE ATTENTION	DANGEROUS AND/OR UN-ROADWORTHY	NOT CHECKED
TYPE: ~~PRESSED STEEL~~ / ~~WIRE POKED~~ / ~~SPLIT~~ RIM / ALLOY FORGING																	
CONDITION	LF										✓						
	RF										✓						
	LR										✓						
	RR										✓						
	SPARE										✓						
3. CONDITION OF BODY KIT / FENDERS AND WHEEL CAPS	LF										✓						
	RF										✓						
	LR										✓						
	RR										✓						

AUTOMOBILE ASSOCIATION OF NAMIBIA
GATE HOUSE
2ND FLOOR, RM 218
TEL: 061-2212215
061-2212293
061-251219

COMMENTS

OK

: TYRES

1. **It is preferable not to mix cross ply and radial ply tyres. They may be fitted in pairs but the radial ply must be fitted to the rear wheels.**
2. **it is advisable to renew tyres which have less than 2mm depth of tread.**
3. **do not mix makes, tread patterns and sizes except in pairs**

	REMOULD	CROSS PLY	RADIAL PLY	TREAD DEPTH IN MM: UNDER 1	1 TO 2	2 TO 4	4 TO 6	OVER 6	UNEVEN WEAR	SATISFACTORY	WORN AND OR DETERIORATED	DAMAGED	UNSUITABLE SIZE AND OR COMBINATION	REQUIRES ATTENTION IN THE NEAR FUTURE	REQUIRES IMMEDIATE ATTENTION	DANGEROUS AND OR UN-ROADWORTHY
LF:						✓				✓						
RF:						✓				✓						
LR:						✓				✓						
RR:						✓				✓						
SPARE:						✓				✓						

	WORN AND OR DETEREORATED	DENTED AND OR DAMAGED	LOOSE AND OR MISALIGNED	BADLY CORRODED	SLIGHTLY CORRODED	OILS AND OR DIRT FOULED	NOT WATER TIGHT	YES	SATISFACTORY	ACCEPTABLE FOR E & AGE MILEAGE RECORDED	BELOW AVERAGE FOR AGE AND MILLEAGE	NO	REQUIRES ATTENTION IN THE NEAR FUTURE	REQUIRES IMMEDIATE ATTENTION	DANGEROUS AND OR UN-ROADWORTHY	NOT CHECKED
D: COOLING SYSTEM																
1: IS COOLANT LEVEL CORRECT								✓								
2: IS COOLANT CONTAMINATED BY RUST/OIL OR SLUGDE												✓				
3 : VISIBLE CONDITION OF RADIATOR										✓						
EXPANSION TANK										✓						
HOSES										✓						
HEATER HOSES										✓						
FAN BELTS										✓						
FAN										✓						
4: ARE THERE ANY LEAKS FROM? RADIATOR												✓				
HOSE PIPES												✓				
HEATER HOSES												✓				
CYLINDER HEAD GASKET												✓				
~~GLOW / HEATER PLUGS~~																
PUMP												✓				
SPARK PLUGS												✓				
THERMOSTAT HOUSING												✓				

1: Oil and fuel consumption tests are not carried out 2: sparking plugs are not removed
3: it is not possible to locate oil leaks accurately on a dirty engine

E: ENGINE

VISIBLE ENGINE CONDITIONS OF																
1: ~~HT CABLES~~																
2: ~~LT CABLES~~																
3: TURBO																
4: BATTERY CABLES										✓						
5: ~~INTER COOLER~~																
6: ~~CONTACT BREAKER~~																
7: ~~SUPER CHARGER~~																
8: ~~DISTRIBUTOR~~ / MODULE / ~~MAGNETO~~										✓						
9: ENGINE MOUNTINGS SIDES										✓						
FRONT REAR										✓						
10: DRIVING BELTS										✓						
11: OIL LEVEL AND CONDITION										✓						
12: IS THERE EVIDENCE OF WATER CONTAMINATION?												✓				
13:DOES OIL PRESSURE WARNING LIGHT OPERATE CORRECTLY?								✓								
14: OIL PRESURE GAUGE READING PSI								KPH TOP GEAR				PSI				

AUTOMOBILE ASSOCIATION OF KENYA
GATE HOUSE
2ND FLOOR, RM 218
TEL: 051-2213215
051-22 7293
0720561719
NAKURU BRANCH

COMMENTS

OK

E: ENGINE CONTINUED		CRACKED	WORN AND OR DETERIORATED	DENTED AND OR DAMAGED	LOOSE AND OR MISALIGNED	BADLY CORRODED	SLIGHTILY CORRODED	OILS AND/ OR DIRT FOULED	NOT WATER TIGHT	YES	SATSFACTORY	ACCEPTABLE FOR MILEAGE AND MILEAGE RECORDED	BELOW AVERAGE FOR AGE AND MILEAGE RECORDED	NO	REQUIRES ATTENTION IN THE NEAR FUTURE	REQUIRES IMMEDIATE ATTENTION	DANGEROUS AND OR UN-ROADWORTHY	NOT CHECKED
12: IS THERE EVIDENCE OF EXCESSIVE LEAKS?														✓				
13: IS THERE EVIDENCE OF EXCESSIVE OIL FUMES														✓				
14: NOISE LEVEL IN :	VALVE OPERATING MECHANISM											✓						
	BEARINGS											✓						
	PISTON / SMALL END ASSEMBLE											✓						
15: DOES EXHAUST EMISION INDICATE	RICH MIXTURE													✓				
	ABNORMAL OIL CONSUMPTION													✓				
16: CYLINDER POWER VARIATION	1 2 3 4 5 6 7 8											✓						
COMMENTS																		

Ok

F : ELECTRICAL EQUIPMENT

CONDITION WHERE POSSIBLE OF 1: BATTERY												✓						
2: BATTERY MOUNTING												✓						
3: WIRING												✓						
CONDITION AND FUNCTION OF 4: HEADLIGHTS	L:											✓						
	R:											✓						
5: PARKING LIGHTS	L:											✓						
	R:											✓						
6: REAR LIGHTS	L:											✓						
	R:											✓						
8: TURN INDICATORS	LF:											✓						
	RF:											✓						
9: ECU UNIT / ECM UNIT	LF:											✓						
	RF											✓						
10 : ~~SPOT LIGHTS / ROOF LIGHTS~~	L:											✓						
	R:																	
11: REVERSING LIGHTS	L:											✓						
	R:											✓						
12: NUMBER PLATE LIGHTS	L:											✓						
	R:											✓						

ARE CONDITION & FUNCTION SATISFACTORY OF:

13 : COURTESY LIGHTS												✓						
14: STARTER												✓						
15: DYNAMO / ALTERNATOR												✓						
16: HORN(S)												✓						
17: IGNITION WARNING LIGHT												✓						
18: MAIN BEAM WARNING LIGHT												✓						
19: PANEL LIGHTS												✓						
19: LEVEL OF ELECTROLYTE CORRECT?												✓						
COMMENTS																		

AUTOMOBILE ASSOCIATION OF KENYA
GATE HOUSE
2ND FLOOR, RM 218
TEL: 051-2212215
051-22:7293
0729561719
NAKURU

Ok

G : FUEL SYSTEM

	WORN AND OR DETERIORATED	DENTED AND OR DAMAGED	LOOSE AND OR MISALIGNED	BADLY CORRODED	SLIGHTILY CORRODED	OILS AND/ OR DIRT FOULED	YES	SATSFACTORY	ACCEPTABLE FOR MILEAGE AND MILEAGE RECORDED	BELOW AVERAGE FOR AGE AND MILEAGE RECORDED	NO	REQUIRES ATTENTION IN THE NEAR FUTURE	REQUIRES IMMEDIATE ATTENTION	DANGEROUS AND OR UN-ROADWORTHY	NOT CHECKED
CONDITION (WHERE VISIBLE) OF CARBURETOR(S)															
INJECTION SYSTEM OR ~~HYBRID SYSTEM~~									✓						
~~INJECTOR PUMP~~															
FUEL PUMP									✓						
CONTROLS									✓						
ACCELERATOR PEDAL & LINKAGE									✓						
FUEL TANK									✓						
FUEL PIPES									✓						
FLEXIBLE HOSES									✓						
AIR CLEANER									✓						
IS THERE EVIDENCE OF FUEL LEAKS?											✓				
IS TUNING NECESSARY?											✓				
IS IDLING SATISFACTORY?							✓								

COMMENTS

Ok

H: FRAME , UNDERSIDE, EXHAUST

IS UNDERSEALING APPLIED?							✓								
IS CONDITION SATISFACTORY							✓								
IS THERE EVIDENCE OF 1 : CORROSION											✓				
2 : DAMAGE											✓				
3 : REPAIRS											✓				
4 : CONDITION OF SPRINGS/SUSPENSION MOUNTING LF:									✓						
RF:									✓						
LR:									✓						
RR:									✓						
5 : DAMPER MOUNTINGS LF:									✓						
RF:									✓						
LR:									✓						
RR:									✓						
6 : UNDER WINGS LF:									✓						
RF:									✓						
LR:									✓						
RR:									✓						

AUTOMOBILE ASSOCIATION OF KENYA
NAKURU BRANCH
GATE HOUSE
2ND FLOOR, RM 213
TEL: 051-2218215
061-2217293
0720561719

BOX SECTIONS									✓						
CROSS MEMBERS									✓						
FRONT SUB FRAME									✓						
REAR SUB FRAME									✓						

UNDER FLOOR PRESSINGS									✓						
FRONT EXHAUST PIPES									✓						
MANIFOLD									✓						
SILENCERS									✓						
REAR EXHAUST PIPE(S)									✓						
EXHAUST MOUNTINGS									✓						

COMMENTS

Ok

I : REAR SUSPENSION

		WORN AND OR DETERIORATED	DENTED AND OR DAMAGED	LOOSE AND OR MISALIGNED	BADLY CORRODED	SLIGHTILY CORRODED	OILS AND/ OR DIRT FOULED	YES	SATSFACTORY	ACCEPTABLE FOR MILEAGE AND MILEAGE RECORDED	BELOW AVERAGE FOR AGE AND MILEAGE RECORDED	NO	REQUIRES ATTENTION IN THE NEAR FUTURE	REQUIRES IMMEDIATE ATTENTION	DANGEROUS AND OR UN-ROADWORTHY	NOT CHECKED	NOT SEEN/ MISSING
1 : CONDITION OF : SPRINGS	L:									✓							
	R:									✓							
2 : DAMPERS	L:									✓							
	R:									✓							
3 : BUMP STOPS	~~L:~~																
	~~R:~~																
4 : HYDROLASTIC UNITS	~~L:~~																
	~~R:~~																
5 : HYDROLASTIC PIPES	~~L:~~																
	~~R:~~																
6 : ANTI ROLLE BAR										✓							
7 : ARE HUB BEARINGS NOISY?	L:											✓					
	R:											✓					

COMMENTS

OK

J : FRONT SUSPENSION AND STEERING

CONDITION AND OPERATION OF 1 : SPRING	L:									✓							
	R:									✓							
2 : DAMPERS	L:									✓							
	R:									✓							
3 : BUMP STOPS	~~L:~~																
	~~R:~~																
4 : HYDROLASTIC PIPES	~~L:~~																
	~~R:~~																
5 : HYDROLASTIC PIPES	~~L:~~																
	~~R:~~																
6 : ANTI ~~ROLLER BAR~~																	
7 : STEERING BOX / RACK										✓							
8 : STEERING JOINTS	L:									✓							
	R:									✓							
9 : POWER STEERING OIL LEAKAGES										✓							
10: RODS , BALL JOINTS AND ARMS	L:									✓							
	R:									✓							
	C:									✓							
11: RUBBER BOOTS										✓							
(PLAY IN) 12: STEERING WHEEL										✓							
13: WHEEL BEARING	(LEFT/RIGHT)									✓							
14: SWIVEL PINS & BEARINGS	(LEFT/RIGHT)									✓							
15: WISH BONE PIVOTS	(LEFT/RIGHT)									✓							
16: ARE WHEEL BEARINGS NOISY?	L:											✓					
	R:											✓					
17: IS A FULL CHECK OF STEERING GEOMETRY NECESSARY?												✓					

COMMENTS

OK

AUTOMOBILE ASSOCIATION OF KENYA
GATE HOUSE
2nd FLOOR, RM 218
TEL: 051-2212215
051-2212293
0720561719
NAKURU BRANCH

K: GEAR BOX

	WORN AND OR DETERIORATED	DENTED AND OR DAMAGED	LOOSE AND OR MISALIGNED	BADLY CORRODED	SLIGHTILY CORRODED	OILS AND/ OR DIRT FOULED	NOT WATER TIGHT	YES	SATSFACTORY	ACCEPTABLE FOR MILEAGE AND MILEAGE RECORDED	BELOW AVERAGE FOR AGE AND MILEAGE RECORDED	NO	REQUIRES ATTENTION IN THE NEAR FUTURE	REQUIRES IMMEDIATE ATTENTION	DANGEROUS AND OR UN-ROADWORTHY	NOT CHECKED
1: IS GEAR BOX AUTOMATIC?								✓								
2: IS FLUID LEVEL CORRECT?								✓								
3: IS THERE UNDUE NOISE OR VIBRATION?																
4: CONDITION OF MOUNTINGS										✓						
5: CONDITION OF LINKAGE										✓						
6: DO ALL GEAR SELECTORS FUNCTION SATISFACTORILY?								✓				✓				
7: DOES OVERDRIVE FUNCTION SATSFACTORILY?								✓								
8: DOES INHIBITOR SWITCH FUNCTION SATISFACTORILY?								✓								
9: DO THE FOLLOWING FUNCTION SATISFACTORILY? -SYNCHROMESH								✓								
-AUTOCHANGES								✓								
-KICKDOWN								✓								
10: ~~TRANSFER~~ BOX																
11:DO ANY GEARS DISENGAGE UNDER LOAD?	1	2	3	4	5	6	R									
12: IS THERE EVIDENCE OF EXCESSIVE OIL LEAKS?												✓				

COMMENTS

OK

L: ~~CLUTCH~~ OR TORQUE CONVERTED

1: CLU~~CTH (MANUAL~~)				
2: TORQUE CONVERTER (AUTOMATIC)	✓			
IS THERE EVIDENCE OF 2: EXCESSIVE NOISE?				
3: CREEP?			✓	
4: LEAKS?			✓	
5: SLIP?			✓	
6: JUDDER?			✓	
7: SPIN?			✓	
8: FIERCENESS?			✓	
9: IS THE FLUID LEVEL CORRECT?	✓			

COMMENTS

AUTOMOBILE ASSOCIATION
GATE POUSE
2ND FLOOR, RM 213
TEL: 051-2218215
051-2217299
0729561719
NAKURU

OK

M : TRANSMISSION AND FINAL DRIVE

	WORN AND OR DETERIORATED	DENTED AND OR DAMAGED	LOOSE AND OR MISALIGNED	BADLY CORRODED	SLIGHTILY CORRODED	OILS AND/ OR DIRT FOULED	NOT WATER TIGHT	YES	SATSFACTORY	ACCEPTABLE FOR MILEAGE AND MILEAGE RECORDED	BELOW AVERAGE FOR AGE AND MILEAGE RECORDED	NO	REQUIRES ATTENTION IN THE NEAR FUTURE	REQUIRES IMMEDIATE ATTENTION	DANGEROUS AND OR UN-ROADWORTHY	NOT CHECKED	NOT SEEN /MISSING
1: CONDITION ~~OF PROPELLER SHAFT~~ ~~F:~~																	
~~REAR:~~																	
FRONT DRIVE SHAFTS INNER L:										✓							
INNER R:										✓							
OUTER L:										✓							
OUTER R										✓							
4 WD ~~WITH REAR DRIVE SHAFTS~~ ~~L:~~																	
~~R:~~																	
2: ~~PROPELLER SHAFT~~ CENTER MOUNTING																	
3: UNIVERSAL COUPLINGS F:																	
REAR:																	
FRONT CV JOINTS INNER L:										✓							
INNER R:										✓							
OUTER L:										✓							
OUTER R:										✓							
4WD WITH REAR CV JOINTS ~~L:~~																	
~~R:~~																	
4: RUBBER BOOTS LF:										✓							
LR:										✓							
RF:										✓							
RR:										✓							
4WD WITH REAR RUBBER BOOTS ~~LF:~~																	
~~LR:~~																	
~~RF:~~																	
~~RR:~~																	
IS THERE EVIDENCE OF EXCESSIVE : 5: NOISE?												✓					
6: OIL LEAKS?												✓					
BACKLASH?												✓					

COMMENTS

Ok

N: BRAKES

1: IS FLUID LEVEL CORRECT?								✓									
CONDITION (WHERE VISIBLE) OF :2: RESERVOIR										✓							
3: MASTER CYLINDER										✓							
4: ABS MODULE										✓							
5: PIPELINES										✓							
6: FLEXIBLE HOSES										✓							
7: UNIONS										✓							
8: FOOT PEDAL AND LINKAGE										✓							
9: HAND BRAKE MECHANISM										✓							
10: DISCS & DRUMS FRONT:										✓							
NOTE: Brakes may be effective even when badly worn. No assessment of the condition of linings, drums or non-visible discs and pads can be given R:										✓							
11 : BREAK PADS F:										✓							
REAR:										✓							
12: IS THERE AND INDICATION OF PRESSURE LOSS?												✓					
FUNCTIONS OF 13: FOOT BRAKES										✓							
14: HAND BRAKES										✓							
15: SERVO SYSTEM										✓							
16: CABLE OR ELECTRIC SYSTEM										✓							
IS THERE EVIDENCE OF : 17: JUDDER?												✓					
18: SQUEAL?												✓					
19: PULL TO THE LEFT / RIGHT?												✓					

COMMENTS

Ok

AUTOMOBILE ASSOCIATION OF NAMIBIA
GATE HOUSE
2ND FLOOR, RM 21
TEL: 061-221225
061-22 7288
0729561719

0 : INSTRUMENTS AND ACCESSORIES	WORN AND OR DETERIORATED	DENTED AND OR DAMAGED	LOOSE AND OR MISALIGNED	BADLY CORRODED	SLIGHTILY CORRODED	OILS AND/ OR DIRT FOULED	NOT WATER TIGHT	YES	SATSFACTORY	ACCEPTABLE FOR MILEAGE AND MILEAGE RECORDED	BELOW AVERAGE FOR AGE AND MILEAGE RECORDED	NO	REQUIRES ATTENTION IN THE NEAR FUTURE	REQUIRES IMMEDIATE ATTENTION	DANGEROUS AND OR UN-ROADWORTHY	NOT CHECKED
1: CONDITION AND FUNCTION OF 1: WIND SCREEN WIPERS L:										✓						
R:										✓						
2. REAR WIPER :										✓						
3: FRONT WINDSCREEN WASHERS L:										✓						
R:										✓						
4:REAR WIND SCREEN WASHER										✓						
5: DEMISTERS F:										✓						
R:										✓						
6: VENTILATION SYSTEMS										✓						
7: SPEEDOMETER										✓						
8: MILEAGE RECORDER										✓						
7: FUEL GAUGE										✓						
9:HEATER										✓						
10: AIR CONDITIONER										✓						
11: TEMPERATURE GAUGE										✓						
12: SEAT BELTS								✓								
B.S.I APPROVED?								✓								
13: DOES INDICATOR SELF CANCEL?								✓								

NOTE The functions of the speedometer, mileage and Temperature gauge are checked on the road test, but the accuracy of These and other gauges cannot be verified

Q: ROAD TEST										
EASE OF STARTING : 1: COLD		✓								
2: HOT		✓								
3: PERFORMANCE		✓								
4: GENERAL HANDLING		✓								

COMMENTS

7

SPECIAL COMMENTS

General handling & performance of the subject vehicle was found to be good.

ECONOMICAL LIFE

7

AUTOMOBILE ASSOCIATION OF KENYA
GATE HOUSE
2ND FLOOR, RM 2
TEL: 051-2213216
051-22
0729561719
NAKURU BRANCH

DISCREPANCIES NOTED

NONE

ESSENTIAL REPAIRS

7

DESIRABLE REPAIRS

7

EXTRAS

ABS, power Steering, Fm CD Navigation Screen radio, Dual SRS airbags, Alloy rims, bout wipes rear Spoiler with light, Cup holders, rear Wiper Camera,

REPORT HANDED / POSTED TO MEMBER ON 15 / 08 / 2025

EXAMINERS : NAME HILLARY SIGEI SIGNATURE

AUTOMOBILE ASSOCIATION OF KENYA
NAKURU BRANCH
GATE HOUSE
2ND FLOOR, RM 218
TEL: 051-2213215
051-2217293
0729561719