| TotalEnergies Marketing Kenya Limited | SAFE TO LOAD REPORT | Date of control 19/06/2025 |
|---|---|---|
| | | N° of control 2506190001 |

| GENERAL INFORMATIONS | |
|---|---|
| **Place of control:** MOMBASA JOINT TERMINAL SHIMANZI | **Transporter:** A.O. BAYUSUF & SONS LIMITED |
| **Start time:** 8:18 | **Prime mover / rigid ID:** KDQ631Z |
| **Inspector:** MARK OSUSA | **Prime mover mileage:** 54021 |
| **Co inspector :** | **Trailer ID:** ZD2004 |
| **Product:** | **Vehicle tag:** |
| **Driver:** JARED MOSE, 22338172 | |

| PREVIOUS SAFE TO LOAD | **Date:** 13/06/2025<br>**Status of the vehicle:** Accepted<br>**Expected repairs have been carried out:** |
|---|---|

## POINTS OF CONTROL AND RESULT

| Common checks | Result | Comments |
|---|---|---|
| Are all lights working, With no cracked casing | Yes | |
| No leaks visible (Engine/Gearbox/Fueltank) | Yes | |
| OBC functionality | Yes | |
| The cabin clean and free from loose objects | Yes | |
| First Aid Box available fully equipped, and with no expired items | Yes | |
| Has the vehicle undergone Brakes maintenance/repairs after the last trip or experienced brakes malfunction | Yes | |
| Visibility: side mirrors, windows, Wind screen, wipers | Yes | |
| Tyres- Are they same on all axles, All nuts present, with right pressure | Yes | |
| Technical vetting of the truck | Yes | |
| Visibility: side mirrors, windows, Wind screen, wipers | Yes | |
| Safety belt (3 fastening points) | Yes | |
| Lighting | Yes | |
| Fire extinguisher | Yes | |
| Wheel/Rims | Yes | |

| Common checks | Result | Comments |
|---|---|---|
| Tyres- Are they same on all axles, All nuts present, with right pressure | Yes | |
| Fifth wheel and king pin (for semi trailer and trailer hitch) | Yes | |
| Marking and stickers | Yes | |
| Emergency phone number | Yes | |
| Brake test | Yes | |

| Driver | Result | Comments |
|---|---|---|
| Driver confirmed fit to drive (Not on medication,Drugs or Fatigue) | Yes | |
| Confirm that the Driver has a valid OBC (blue)key? | Yes | |
| Driver's accreditation/licence | Yes | |
| Driver PPE | Yes | |

| Truck equipment | Result | Comments |
|---|---|---|
| 2 early warning devices: (triangles,cones) | Yes | |
| Wheel chocks- Are they wooden/Aluminium, Not broken | Yes | |
| Proper closing and fastening of the back and/or side doors | Yes | |
| Condition of the bed/floor | Yes | Sealed. |
| Stoppers or lashing (x3 if stacking) | Yes | |
| Condition of vinyl cover (tarpaulin) | Yes | n/a |
| Presence and strength of the sides boards | Yes | |
| Rear loading lift gate | Yes | n/a |
| Condition of the container | Yes | Scratches noted on container. |
| Condition of the semi-trailer landing gear legs | Yes | |

| GLOBAL RESULT | **THE VEHICLE IS : Accepted**<br><br>**General comments:** |
|---|---|

| TotalEnergies Marketing Kenya Limited | SAFE TO LOAD<br>REPORT | Date of control<br>19/06/2025 |
|---|---|---|
| | | N° of control<br>2506190001 |

## PICTURES TAKEN DURING THE SAFE TO LOAD

| Point of control | Picture |
|---|---|