TotalEnergies Marketing Kenya Limited	SAFE TO LOAD REPORT	Date of control 19/06/2025
		N° of control 2506190009

GENERAL INFORMATIONS	
Place of control: NAIROBI JOINT DEPOT	**Transporter:** DIKUS TRANSPORTERS LIMITED
Start time: 6:11	**Prime mover / rigid ID:** KCN020T
Inspector: GERALD NGUGI	**Prime mover mileage:** 145216
Co inspector :	**Trailer ID:** NA
Product: Hydrocarbon, Lubricants, Heavy fuel	**Vehicle tag:**
Driver: Morrison Maina-ID:22850489	

PREVIOUS SAFE TO LOAD	**Date:** 18/06/2025 **Status of the vehicle:** Accepted **Expected repairs have been carried out:**

POINTS OF CONTROL AND RESULT

Common checks	Result	Comments
Technical vetting of the truck	Yes	
Visibility: side mirrors, windows, Wind screen, wipers	Yes	
Safety belt (3 fastening points)	Yes	
Are all lights working, With no cracked casing	Yes	
Fire extinguisher	Yes	
Wheel/Rims	Yes	
Tyres- Are they same on all axles, All nuts present, with right pressure	Yes	
Fifth wheel and king pin (for semi trailer and trailer hitch)	Yes	
Marking and stickers	Yes	
Condition of welds and absence of cracks	Yes	
Emergency phone number	Yes	
General condition of electrical wiring	Yes	
Earthing studs	Yes	
Brake test	Yes	
No leaks visible (Engine/Gearbox/Fueltank)	Yes	

Common checks	Result	Comments
Bottom valves and compartments manholes and cover domes sealing mechanism confirmed OK with bolts and nuts welded	Yes	
OBC functionality	Yes	
Valid Fire Inspection and Certification for Tankers	Yes	
The cabin clean and free from loose objects	Yes	
Fitted with Spark arrester	Yes	
First Aid Box available fully equipped, and with no expired items	Yes	
Has the vehicle undergone Brakes maintenance/repairs after the last trip or experienced brakes malfunction	Yes	
Visibility: side mirrors, windows, Wind screen, wipers	Yes	
Tyres- Are they same on all axles, All nuts present, with right pressure	Yes	

Driver	Result	Comments
Driver's accreditation	Yes	
Driver's PPE	Yes	
Driver confirmed fit to drive (Not on medication,Drugs or Fatigue)	Yes	
Confirm that the Driver has a valid OBC (blue)key?	Yes	

Truck equipment	Result	Comments
Battery cut off switch (cabin or outside)	Yes	
2 early warning devices (triangles, cones)	Yes	
Wheel chocks	Yes	

Hydrocarbon, lubricants, heavy fuel	Result	Comments
Ladder, handrail, upper walkway	Yes	
Composite hoses	Yes	

Bulk gas	Result	Comments
Gauge or system check level		
Certification document of the trucks and test date		
Checking that the truck is under pressure		

Bulk gas	Result	Comments
Bottom valves		

GLOBAL RESULT	**THE VEHICLE IS : Accepted** **General comments:** ok to load

TotalEnergies Marketing Kenya Limited	SAFE TO LOAD REPORT	Date of control 19/06/2025
		N° of control 2506190009

PICTURES TAKEN DURING THE SAFE TO LOAD

Point of control	Picture