| TotalEnergies Marketing Kenya Limited | SAFE TO LOAD REPORT | Date of control 20/06/2025 |
|---|---|---|
| | | N° of control 2506200043 |

| GENERAL INFORMATIONS | |
|---|---|
| **Place of control:** NAKURU KPC | **Transporter:** DIKUS TRANSPORTERS LIMITED |
| **Start time:** 9:18 | **Prime mover / rigid ID:** KCN509G |
| **Inspector:** Julius Raute | **Prime mover mileage:** 305480 |
| **Co inspector :** | **Trailer ID:** ZF7781 |
| **Product:** Hydrocarbon, Lubricants, Heavy fuel | **Vehicle tag:** |
| **Driver:** Mohamed 11503902 Edin | |

| PREVIOUS SAFE TO LOAD | **Date:** 19/06/2025<br>**Status of the vehicle:** Accepted<br>**Expected repairs have been carried out:** |
|---|---|

## POINTS OF CONTROL AND RESULT

| Common checks | Result | Comments |
|---|---|---|
| Technical vetting of the truck | Yes | |
| Visibility: side mirrors, windows, Wind screen, wipers | Yes | |
| Safety belt (3 fastening points) | Yes | |
| Are all lights working, With no cracked casing | Yes | |
| Fire extinguisher | Yes | |
| Wheel/Rims | Yes | |
| Tyres- Are they same on all axles, All nuts present, with right pressure | Yes | |
| Fifth wheel and king pin (for semi trailer and trailer hitch) | Yes | |
| Marking and stickers | Yes | |
| Condition of welds and absence of cracks | Yes | |
| Emergency phone number | Yes | |
| General condition of electrical wiring | Yes | |
| Earthing studs | Yes | |
| Brake test | Yes | |
| No leaks visible (Engine/Gearbox/Fueltank) | Yes | |

| Common checks | Result | Comments |
|---|---|---|
| Bottom valves and compartments manholes and cover domes sealing mechanism confirmed OK with bolts and nuts welded | Yes | |
| OBC functionality | Yes | |
| Valid Fire Inspection and Certification for Tankers | Yes | |
| The cabin clean and free from loose objects | Yes | |
| Fitted with Spark arrester | Yes | |
| First Aid Box available fully equipped, and with no expired items | Yes | |
| Has the vehicle undergone Brakes maintenance/repairs after the last trip or experienced brakes malfunction | Yes | |
| Visibility: side mirrors, windows, Wind screen, wipers | Yes | |
| Tyres- Are they same on all axles, All nuts present, with right pressure | Yes | |

| Driver | Result | Comments |
|---|---|---|
| Driver's accreditation | Yes | |
| Driver's PPE | Yes | |
| Driver confirmed fit to drive (Not on medication,Drugs or Fatigue) | Yes | |
| Confirm that the Driver has a valid OBC (blue)key? | Yes | |

| Truck equipment | Result | Comments |
|---|---|---|
| Battery cut off switch (cabin or outside) | Yes | |
| 2 early warning devices (triangles, cones) | Yes | |
| Wheel chocks | Yes | |

| Hydrocarbon, lubricants, heavy fuel | Result | Comments |
|---|---|---|
| Ladder, handrail, upper walkway | Yes | |
| Composite hoses | Yes | |

| Bulk gas | Result | Comments |
|---|---|---|
| Gauge or system check level | | |
| Certification document of the trucks and test date | | |
| Checking that the truck is under pressure | | |

| Bulk gas | Result | Comments |
|---|---|---|
| Bottom valves | | |

| GLOBAL RESULT | **THE VEHICLE IS : Accepted**<br><br>**General comments:** |
|---|---|

| TotalEnergies Marketing Kenya Limited | SAFE TO LOAD<br>REPORT | Date of control<br>20/06/2025 |
|---|---|---|
| | | N° of control<br>2506200043 |

## PICTURES TAKEN DURING THE SAFE TO LOAD

| Point of control | Picture |
|---|---|