## Inspection by AA KENYA

INSPECTION REPORT:

**TOTAL Inspection_Kenya_2025_550_A**

**Transporter:**
DIKUS TRANSPORTERS

**Tractor Registration Number:**
KCN509G

**Tractor Chasis Number:**
9BSP6X40003895401

**Inspection Date**
02/01/2025

**Inspection Address**
NAIROBI.

**Inspection Result**
**COMPLIANT**

## Summary - Interdiction

| | Nb of not compliant I criteria |
|---|---|
| 1. VEHICLE IDENTIFICATION | Compliant |
| 2. VISIBILITY | Compliant |
| 3. LIGHTING, SIGNALING | Compliant |
| 4. BRAKING SYSTEM | Compliant |
| 5. STEERING | Compliant |
| 6. CONTACT POINTS WITH THE GROUND | Compliant |
| 7. CHASSIS AND CHASSIS ACCESSORIES | Compliant |
| 8. EQUIPMENT | Compliant |
| 9. MECHANICAL SYSTEM | Compliant |
| 10. TANK | Compliant |

## Summary - Maintenance Plan

| | Nb of not compliant I criteria |
|---|---|
| 1. VEHICLE IDENTIFICATION | Compliant |
| 2. VISIBILITY | Compliant |
| 3. LIGHTING, SIGNALING | Compliant |
| 4. BRAKING SYSTEM | Compliant |
| 5. STEERING | Compliant |
| 6. CONTACT POINTS WITH THE GROUND | Compliant |
| 7. CHASSIS AND CHASSIS ACCESSORIES | Compliant |
| 8. EQUIPMENT | Compliant |
| 9. MECHANICAL SYSTEM | Compliant |
| 10. TANK | Compliant |

## Summary - Without Interdiction

| | Nb of not compliant I criteria |
|---|---|
| 1. VEHICLE IDENTIFICATION | Compliant |
| 2. VISIBILITY | Compliant |
| 3. LIGHTING, SIGNALING | Compliant |
| 4. BRAKING SYSTEM | Compliant |
| 5. STEERING | Compliant |
| 6. CONTACT POINTS WITH THE GROUND | Compliant |
| 7. CHASSIS AND CHASSIS ACCESSORIES | Compliant |
| 8. EQUIPMENT | Compliant |
| 9. MECHANICAL SYSTEM | Compliant |
| 10. TANK | Compliant |

## GENERAL INFORMATION

| | |
|---|---|
| Inspection Date: **02/01/2025** | Visit Date: **02/01/2025** |
| Inspector Name: **SAMUEL GICHUKI** | Counter Visit Date: |
| Transporter (Contractor): **DIKUS TRANSPORTERS** | Registration Number Tractor / Heavy Load Truck: **KCN509G** |
| Contractor (Subcontractor): **N/A** | Visit Date: **02/01/2025** |
| Inspection Date: **02/01/2025** | Registration Number Semi-Trailer/Trailer: **ZF7781** |
| Addres Of Client: **NAIROBI, NAIROBI, NAIROBI** | Chasis Number: **9BSP6X40003895401** |
| Name Of Client: **TOTALENERGIES MARKETING KENYA PLC** | Semi-Trailer/Trailer Chasis Number: **BIL26260** |
| Phone Number Of Client: **+254721723452** | Vehicle Model: |
| Mileage: **305481 KM** | Additional Information 2: **N/A** |

## Non-Conformity

| NC Status | Photo | Attachment |
|---|---|---|
| | | |

## TECHNICAL CONTROL - GRID

### 1. VEHICLE IDENTIFICATION

#### Document Presented

| | Control | Cause | Notes |
|---|---|---|---|
| 1.1.1. Vehicle registration document | Compliant | | Documentation checked by TMK |
| 1.1.2. Vehicle maintenance log | Compliant | | |
| 1.1.3. Reports of previous visits | N/A | | |

#### Registration Number

| | Control | Cause | Notes |
|---|---|---|---|
| 1.2. License plate | Compliant | | |

#### Plates And Inscription

| | Control | Cause | Notes |
|---|---|---|---|
| 1.3.1. Stamp on the chassis tractor | Compliant | | |
| 1.3.2. Stamp on the chassis trailer | Compliant | | |

#### Vehicle Presentation

| | Control | Cause | Notes |
|---|---|---|---|
| 1.4.0. Presentation and cleanliness | Compliant | | |
| 1.4.1. Vehicle load sheet | Compliant | | |
| 1.4.2. Length | Compliant | | Documentation checked by TMK |
| 1.4.3. Width | Compliant | | Documentation checked by TMK |
| 1.4.4. GW | Compliant | | |
| 1.4.5. GCWR | Compliant | | Documentation checked by TMK |

## 2. VISIBILITY

### Windows

| | Control | Cause | Notes |
|---|---|---|---|
| 2.1.1. Windshield | Compliant | | |

### Mirrors

| | Control | Cause | Notes |
|---|---|---|---|
| 2.2.1. Rear view mirror | Compliant | | |
| 2.2.2. Wing Mirrors | Compliant | | |
| 2.2.2.1. Two standard wing mirrors (Class II) | Compliant | | |
| 2.2.2.2. Two wing mirrors large angle (Class IV) | Compliant | | |
| 2.2.2.3. Vehicle built before 01/01/2015: One wing or the rear parabolic mirror (front mirror - class VI) | Compliant | | |
| 2.2.2.4. Vehicle built after 01/01/2015: One wing or the rear parabolic mirror (front mirror - class VI) [CV] | Compliant | | |
| 2.2.2.5. Vehicle built before 01/01/2015: One wing docking mirror passenger side (Class V) or one convex glass in low part of the door | Compliant | | |
| 2.2.2.6. Vehicule built after 01/01/2015: One wing docking mirror passenger side (Class V) or one convex glass in low part of the door [CV] | Compliant | | |

### Accessories

| | Control | Cause | Notes |
|---|---|---|---|
| 2.3.1. Front windshield wipers | N/A | | |
| 2.3.2. Front windshield whasher | Compliant | | |

## 3. LIGHTING, SIGNALING

### Lighting

| | Control | Cause | Notes |
|---|---|---|---|
| 3.1.1. Dipped headlight | Compliant | | |
| 3.1.2. High beam headlights | Compliant | | |

### Signaling

| | Control | Cause | Notes |
|---|---|---|---|
| 3.2.1. Sidelights | Compliant | | |
| 3.2.2. Direction indicator lamps | Compliant | | |
| 3.2.3. Hazard lights | Compliant | | |
| 3.2.4. Rear red light | Compliant | | |
| 3.2.5. Brake light | Compliant | | |
| 3.2.6. Rear license plate light | Compliant | | |
| 3.2.7. Rear fog lamp | N/A | | |
| 3.2.8. Reversing light | Compliant | | |
| 3.2.9. End-outline makers lamp | Compliant | | |
| 3.2.10. Side marker lamp | Compliant | | |
| 3.2.11. Reflector | Compliant | | |
| 3.2.12. Additional rear signaling | Compliant | | |
| 3.2.13. Special lights | N/A | | |

### Lighting controls

| | Control | Cause | Notes |
|---|---|---|---|
| 3.3.1. Lighting and signaling controls (Condition and functioning) | Compliant | | |
| 3.3.2. High beam light indicator | Compliant | | |
| 3.3.3. Direction indicator light | Compliant | | |

### Wiring

| | Control | Cause | Notes |
|---|---|---|---|
| 3.4.1. Wiring | Compliant | | |
| 3.4.2. Electrical bonding (Tractor, Trailer) | Compliant | | |
| 3.4.3. Battery terminal protector / Insulating battery cover | Compliant | | |
| 3.4.4. Battery main switch | Compliant | | |
| 3.4.5. Fuse box | Compliant | | |

## 4. BRAKING SYSTEM

### Measurements -Tests

| | Control | Cause | Notes |
|---|---|---|---|
| 4.1.1. Service brake | Compliant | | 46% |
| 4.1.2. Emergency brake | Compliant | | |
| 4.1.3. Parking brake | Compliant | | 34% |
| 4.1.4. Breakaway brake | Compliant | | |
| 4.1.6. Independence of the brake systems | Compliant | | |
| 4.1.8. Unbalance of service brake | Compliant | | |

### Air and Hydraulic

| | Control | Cause | Notes |
|---|---|---|---|
| 4.2.1. Air-brake reservoir | Compliant | | |
| 4.2.2. Reservoir purge | Compliant | | |
| 4.2.3. Compressor | Compliant | | |
| 4.2.4. Air Drier Filter | Compliant | | |
| 4.2.5. Brake system | Compliant | | |
| 4.2.6. Hydraulic system | N/A | | |
| 4.2.7. Brake hose | Compliant | | |
| 4.2.8. Valve | Compliant | | |
| 4.2.9. Brake pressure regulating valve | Compliant | | |
| 4.2.10. Brake hose couplers (Liaison pneumatic tank tractor) | Compliant | | |

### Control elements

| | Control | Cause | Notes |
|---|---|---|---|
| 4.3.1. Service brake pedal test | Compliant | | |
| 4.3.2. Emergency brake control tes | Compliant | | |
| 4.3.3. Parking brake control test | Compliant | | |
| 4.3.4. Parking brake cable and linkage - Trailer only | Compliant | | |
| 4.3.5. Retarder control | Compliant | | |

### Braking system

| | Control | Cause | Notes |
|---|---|---|---|
| 4.4.1. Brake disc (Visual control no disassembling) | Compliant | | |
| 4.4.2. Brake chamber (Visual control no disassembling) | Compliant | | |

| | | | |
|---|---|---|---|
| 4.4.3. Caliper (Visual control no disassembling) | Compliant | | |
| 4.4.4. Brake drum (Visual control no disassembling) | Compliant | | |
| 4.4.5. Brake pad and lining (Visual control no disassembling) | Compliant | | |
| 4.4.6. Brake-actuating lever | Compliant | | |
| 4.4.7. Drive cam pin | Compliant | | |
| 4.4.8. Retarder | Compliant | | |
| 4.4.9. Antilock braking system (ABS, EBS) | Compliant | | |

### Indicator lights (Dashboard)

| | Control | Cause | Notes |
|---|---|---|---|
| 4.5.1. Service brake warning light [CV] | Compliant | | |
| 4.5.2. Parking brake indicator light [CV] | Compliant | | |
| 4.5.3. Antilock system indicator light [CV] | Compliant | | |
| 4.5.4. Brake-lining wear indicator light (if equipped) | Compliant | | |
| 4.5.5. Insufficient air-flow warning light [CV] | Compliant | | |

## 5. STEERING

### Steering system

| | Control | Cause | Notes |
|---|---|---|---|
| 5.1.1. Steering wheel | Compliant | | |
| 5.1.2. Steering column and linkage | Compliant | | |
| 5.1.3. Steering gearbox | Compliant | | |
| 5.1.4. Steering rod | Compliant | | |
| 5.1.5. Drag link | Compliant | | |
| 5.1.6. Track rod | Compliant | | |
| 5.1.7. Steering ball joint | Compliant | | |
| 5.1.8. Pivot | Compliant | | |
| 5.1.9. Bell crank | Compliant | | |
| 5.1.10. Steering stop | Compliant | | |

### Power steering system

| | Control | Cause | Notes |
|---|---|---|---|
| 5.2.1. Power steering reservoir | Compliant | | |
| 5.2.2. Power steering hoses | Compliant | | |

## 6. CONTACT POINTS WITH THE GROUND

### Axles and suspension system

| | Control | Cause | Notes |
|---|---|---|---|
| 6.1.1. Axles and suspension system [CV] | Compliant | | |
| 6.1.2. Suspension flange [CV] | Compliant | | |
| 6.1.3. Wheel hub [CV] | Compliant | | |
| 6.1.4. Axle and suspension tie-bar [CV] | Compliant | | |
| 6.1.7. Leaf spring [CV] | Compliant | | |
| 6.1.8. Auxiliary leaf springs [CV] | Compliant | | |
| 6.1.9. Spring mounting bracket and shackle [CV] | Compliant | | |
| 6.1.10. Spring clamp | Compliant | | |
| 6.1.11. Spring bolt [CV] | Compliant | | |
| 6.1.12. Lever arm [CV] | Compliant | | |
| 6.1.13. Axle beam [CV] | Compliant | | |
| 6.1.15. Suspension ball joint [CV] | Compliant | | |

| | | | |
|---|---|---|---|
| 6.1.16. Silent-block shock-absorber [CV] | Compliant | | |
| 6.1.17. Shock absorber | Compliant | | |
| 6.1.18. Air suspension bellows [CV] | Compliant | | |
| 6.1.19. Suspension system [CV] | Compliant | | |
| 6.1.20. Stabilizer bar [CV] | Compliant | | |
| 6.1.21. Stabilizer bar silentblocks [CV] | Compliant | | |

### Wheels and tires

| | Control | Cause | Notes |
|---|---|---|---|
| 6.2.1.Wheel rim (Ovalization of the hub carrier part and fixing holes) | Compliant | | |
| 6.2.2. Wheel rim (Bolts) | Compliant | | |
| 6.2.3. Tire (Axle) | Compliant | | |
| 6.2.4. Tire (Retreading and regrooving forbidden) | Compliant | | |
| 6.2.5. Valve caps on tires | Compliant | | |
| 6.2.6. Loose wheel nut indicator | Compliant | | |

## 7. CHASSIS AND CHASSIS ACCESSORIES

### Chassis

| | Control | Cause | Notes |
|---|---|---|---|
| 7.1.1. Side rail and cross-member | Compliant | | |

### Carroserie

| | Control | Cause | Notes |
|---|---|---|---|
| 7.2.1. Cab | Compliant | | |
| 7.2.2. Body | Compliant | | |
| 7.2.3. Tarpaulin | N/A | | |
| 7.2.4. Tailgate | N/A | | |
| 7.2.5. Running board | N/A | | |
| 7.2.6. Door | Compliant | | |
| 7.2.8. Floor | Compliant | | |
| 7.2.9. Trunk | N/A | | |
| 7.2.10. Spare wheel carrier | Compliant | | |
| 7.2.11. Battery | Compliant | | |
| 7.2.12. Stand | Compliant | | |
| 7.2.13. Bumper | Compliant | | |
| 7.2.14. Stone shield | Compliant | | |
| 7.2.15. Underrun protection system | Compliant | | |
| 7.2.17. Side protection system (semi-trailer) | Compliant | | |

## 8. EQUIPMENT

| | Control | Cause | Notes |
|---|---|---|---|
| 8.1. Driver's seat | Compliant | | |
| 8.2. Passenger seat | Compliant | | |
| 8.3.1. Driver's safety belt | Compliant | | |
| 8.3.2. Passenger safety belt | Compliant | | |
| 8.4. Fifth wheel coupling | Compliant | | |
| 8.5.1. Fifth wheel (Condition) | Compliant | | |
| 8.5.2. Fifth wheel (Lubrication) | Compliant | | |
| 8.5.3. Fifth wheel (Locking) | Compliant | | |
| 8.5.4. Fifth wheel (Free play) | Compliant | | |

| | | | |
|---|---|---|---|
| 8.5.5. Fifth wheel (Safety pin) | Compliant | | |
| 8.6.1. Center pin (King pin) 3,5" | Compliant | | |
| 8.8. Pintle hook | Compliant | | |
| 8.9. Pintle eye | Compliant | | |
| 8.10. Drawbar | N/A | | |
| 8.11. Chock block (2) | N/A | | |
| 8.12. Trailer front-end hitch | N/A | | |
| 8.13.1. Classical horn | N/A | | |
| 8.13.2. Reversing horn | Compliant | | |
| 8.14. Extinguisher (presence and validity date) | N/A | | |
| 8.17. Tare plate | Compliant | | |

## 9. MECHANICAL SYSTEM

| | Control | Cause | Notes |
|---|---|---|---|
| 9.1. Engine | Compliant | | |
| 9.2. Accelerator | Compliant | | |
| 9.3. Clutch | N/A | | |
| 9.4. Drive unit | Compliant | | |
| 9.5. Transfer gear box | N/A | | |
| 9.6. Gearbox | Compliant | | |
| 9.7. Drive shaft | N/A | | |
| 9.8. OK | Compliant | | |
| 9.9. Center Bearing | Compliant | | |
| 9.10. Fuel system | Compliant | | |
| 9.11. Fuel tank | Compliant | | |
| 9.12. Additional tank | Compliant | | |
| 9.13. Exhaust manifold | Compliant | | |
| 9.14. Exhaust connection | Compliant | | |
| 9.15. Exhaust silencer | Compliant | | |

## 10. TANK

| | Control | Cause | Notes |
|---|---|---|---|
| 10.1. Identification plate | Compliant | | |
| 10.2. Tare plate (Registration certificate) | Compliant | | |
| 10.3.1. Outside conditions (Distortion) | Compliant | | |
| 10.3.2. Outside conditions (Tank tightness) | Compliant | | |
| 10.4. Fixing and cradles | Compliant | | |
| 10.4.1. Fixing chassis on underframe | Compliant | | |
| 10.5. Protection of upper mechanisms | Compliant | | |
| 10.6. Ladder | Compliant | | |
| 10.7.1. Safety guardrail and walkway (Folding safety guardrail) | Compliant | | |
| 10.7.2. Safety guardrail and walkway (Condition) | Compliant | | |
| 10.10.1. Bottom check valve (internal shutter) on each pipe (Presence) | N/A | | |
| 10.10.2. Bottom check valve (internal shutter) on each pipe (Presence) | N/A | | |
| 10.10.3. Emergency button | Compliant | | |
| 10.11.1. Piping (Condition) | Compliant | | |
| 10.11.2. Piping (Leak) | Compliant | | |
| 10.12.1. Valves (Condition) | Compliant | | |
| 10.12.2. Valves (Leak) | Compliant | | |
| 10.13.1. Hoses and delivery piping | Compliant | | |
| 10.13.2. Hoses carrier | Compliant | | Delivery box sealed |
| 10.13.3. Furling | Compliant | | |

| | | | |
|---|---|---|---|
| 10.14. Hazardous materials warning signs | Compliant | | |
| 10.15.1. Grounding | N/A | | |
| 10.15.2. Pad grounding (equipotential bonding) | Compliant | | |
| 10.15.3. Electric braid tank / Chassis | Compliant | | |

COMMENTS:

COMPLIANT
Brake Test Results:
Service brake - 45%
Parking brake- 34%
TECHNICAL INSPECTION
Ok