SERIAL: AAK67220672

MOTOR VEHICLE VALUATION & INSPECTION

CERTIFICATE

FULL MECHANICAL

This is to certify that the vehicle

Registration Number :	**KDD444D**
Vehicle Make :	**TOYOTA**
Vehicle Model Number :	**Allion**
Chassis Number :	**RTYU-78JHF**
Year of Manufacture :	**2023**

Has been inspected and assessed by AA of Kenya and valued at (Kshs)

4,042,330.33

(FOUR MILLION FORTY TWO THOUSAND THREE HUNDRED THIRTY ONLY)

A detailed report is attached.

Valuation & Inspection Manager

AA KENYA P.O. Box 40087 - 00100. NAIROBI

Valuation & Inspection Officer

Date : 14/10/2025

SERIAL: AAK67220672

MOTOR VEHICLE VALUATION & INSPECTION
FULL MECHANICAL

Insured Name: Jacob Mulama Tel: +254743889076 Email: amos@gmail.com

A Brief Examination and Road Test have been carried out on the following vehicle and the findings are as follows:-

Reg: KDD444D	Make: TOYOTA	Model: Allion	Color: Yellow
YOM: 2023	Country: Japanese	Chassis: RTYU-78JHF	
Drive: NA	Capacity: 4.8	Engine No:	
Registration Date:			

Body	:	All good
Transmission	:	slight issues
Tyres	:	great tyres
Braking	:	all good
Mechanical	:	all good
electrical	:	all good
Steering	:	no issues
Suspension	:	all good

Extras:

No extras specified

Remarks

Vehicle good ðŸ˜Šð‘•

Examiners prices (Kshs) of separately insurable items

NA

Examiner's Opinion (Kshs):

4,042,330.33 (FOUR MILLION FORTY TWO THOUSAND THREE HUNDRED THIRTY)

Forced Sale Value (Kshs):

3,233,864.26 (THREE MILLION TWO HUNDRED THIRTY THREE THOUSAND EIGHT HUNDRED SIXTY FOUR)

Valuation & Inspection Manager

AA KENYA P.O. Box 40087 - 00100. NAIROBI

Valuation & Inspection Officer

Date : 14/10/2025

INSPECTION IMAGES

ENGINE



DASHBOARD



ODORMETER




BACK LEFT TIRE



BACK RIGHT TIRE



FRONT RIGHT TIRE




Valuation & Inspection Manager

Valuation & Inspection Officer

Date : 14/10/2025

INSPECTION IMAGES (CONTINUED)

FRONT LEFT TIRE



Valuation & Inspection Manager

Valuation & Inspection Officer

Date : 14/10/2025

Terms & Conditions

The examiners take every care & precaution during inspections but the AA cannot accept responsibility for claims arising as a result of latent defects or matters of opinion

The AA reserves the right to decline to examine or to report on any vehicle not of standard production or one which has not been in regular road use.

The examination to which this report refers is external only and does not involve dismantling or disturbing any structure, assembly, component or internal mechanism.

Only limited road test is undertaken.

Vehicles over 5 years and those that have been subjected to abnormal use may have serious defects which may not be detected by external examination. The AA will not be held responsible for liability arising out of this.

No indication can be given of the availability of the spare parts for the particular make or model of a vehicle.

Parts that are excessively contaminated by oil or dirt may not be properly examined.

The assessed value given after a brief examination and road test is consistent with the age and condition of the said vehicle. However, it must be emphasized that it bears no relationship with any agreement between buyer and seller which is entirely dependent on willingness of the two parties to a greater or lesser degree.

Where it is stated in the inspection report that some information was supplied by AA a third party, the AA Kenya will not be held responsible for the reliability of the information, if found to be incorrect.

Re-examination after repairs will be carried out at a fee.

The assessed value is based on the date of first registration and the odometer reading being genuine.

Valuation & Inspection Manager

AA KENYA
P.O. Box 40087 - 00100. NAIROBI

Valuation & Inspection Officer

Date : 14/10/2025

COMPREHENSIVE MECHANICAL INSPECTION REPORT

This comprehensive mechanical inspection report provides detailed assessment of all major vehicle components and systems. The inspection follows standardized procedures to evaluate the condition and functionality of each inspected item.

ASSESSMENT CRITERIA LEGEND

SATISFACTORY	Component is in good working condition
ATTENTION REQUIRED	Minor issues requiring attention in near future
IMMEDIATE ATTENTION	Issues requiring prompt attention
DANGEROUS/UNROADWORTHY	Critical safety issues - immediate repair required
NOT CHECKED	Component was not inspected

POSITION CODES

LF = Left Front | RF = Right Front | LR = Left Rear | RR = Right Rear | F = Front | R = Rear | L = Left | C = Center

Valuation & Inspection Manager

AA KENYA P.O. Box 40087 - 00100. NAIROBI

Valuation & Inspection Officer

Date : 14/10/2025

A: BODY WORK

External and internal body components inspection

1. DOORS

LR (Left Rear):	ACCEPTABLE FOR AGE AND MILEAGE	
RF (Right Front):	ACCEPTABLE FOR AGE AND MILEAGE	ACCEPTABLE FOR AGE AND MILEAGE
RR (Right Rear):	ACCEPTABLE FOR AGE AND MILEAGE	
LF (Left Front):	ACCEPTABLE FOR AGE AND MILEAGE	ACCEPTABLE FOR AGE AND MILEAGE

2. DOOR LOCKS

RR (Right Rear):	ACCEPTABLE FOR AGE AND MILEAGE
LF (Left Front):	ACCEPTABLE FOR AGE AND MILEAGE
LR (Left Rear):	ACCEPTABLE FOR AGE AND MILEAGE
RF (Right Front):	ACCEPTABLE FOR AGE AND MILEAGE

3. WINDOWS

LF (Left Front):	ACCEPTABLE FOR AGE AND MILEAGE
LR (Left Rear):	ACCEPTABLE FOR AGE AND MILEAGE
RF (Right Front):	ACCEPTABLE FOR AGE AND MILEAGE
RR (Right Rear):	ACCEPTABLE FOR AGE AND MILEAGE

4. WINDOW WINDERS

RF (Right Front):	ACCEPTABLE FOR AGE AND MILEAGE
RR (Right Rear):	ACCEPTABLE FOR AGE AND MILEAGE
LF (Left Front):	ACCEPTABLE FOR AGE AND MILEAGE
LR (Left Rear):	ACCEPTABLE FOR AGE AND MILEAGE

5. QUARTER LIGHT GLASS

LF (Left Front):	ACCEPTABLE FOR AGE AND MILEAGE
LR (Left Rear):	ACCEPTABLE FOR AGE AND MILEAGE
RF (Right Front):	ACCEPTABLE FOR AGE AND MILEAGE
RR (Right Rear):	ACCEPTABLE FOR AGE AND MILEAGE

6. WINGS OR WING AREA

LF (Left Front):	ACCEPTABLE FOR AGE AND MILEAGE
LR (Left Rear):	ACCEPTABLE FOR AGE AND MILEAGE
RF (Right Front):	ACCEPTABLE FOR AGE AND MILEAGE
RR (Right Rear):	ACCEPTABLE FOR AGE AND MILEAGE

7. QUARTER PANELS

RR (Right Rear):	ACCEPTABLE FOR AGE AND MILEAGE
LF (Left Front):	ACCEPTABLE FOR AGE AND MILEAGE
LR (Left Rear):	ACCEPTABLE FOR AGE AND MILEAGE
RF (Right Front):	ACCEPTABLE FOR AGE AND MILEAGE

Valuation & Inspection Officer

AA OF K NAIROBI
P.O. Box 40087 - 00100

Date : 14/10/2025

8. BOOT OR TAILGATE LOCK

ACCEPTABLE FOR AGE AND MILEAGE

9. BOOT INTERIOR

ACCEPTABLE FOR AGE AND MILEAGE

10. BONNET PANEL

ACCEPTABLE FOR AGE AND MILEAGE

11. BONNET LOCK

ACCEPTABLE FOR AGE AND MILEAGE

12. RADIATOR GRILLE

ACCEPTABLE FOR AGE AND MILEAGE

13. ROOF

ACCEPTABLE FOR AGE AND MILEAGE

14. WINDSCREEN

ACCEPTABLE FOR AGE AND MILEAGE

15. REAR WINDOW

ACCEPTABLE FOR AGE AND MILEAGE

16. BODY SILLS

F (WING & BOOT MIRROR ACCEPTABLE FOR AGE AND MILEAGE
R (WING & BOOT MIRROF ACCEPTABLE FOR AGE AND MILEAGE

17. JACKING POINTS

L (EXTERNAL MIRRORS): ACCEPTABLE FOR AGE AND MILEAGE
R (WING & BOOT MIRROF ACCEPTABLE FOR AGE AND MILEAGE

18. EXTERNAL MIRRORS

L (EXTERNAL MIRRORS): ACCEPTABLE FOR AGE AND MILEAGE
R (WING & BOOT MIRROF ACCEPTABLE FOR AGE AND MILEAGE

19. WING & BOOT MIRROR

F (WING & BOOT MIRROR ACCEPTABLE FOR AGE AND MILEAGE
R (WING & BOOT MIRROF ACCEPTABLE FOR AGE AND MILEAGE

20. BUMPERS

F (WING & BOOT MIRROR ACCEPTABLE FOR AGE AND MILEAGE
R (WING & BOOT MIRROF ACCEPTABLE FOR AGE AND MILEAGE

21. BUMPER VALANCE

F (WING & BOOT MIRROR ACCEPTABLE FOR AGE AND MILEAGE
R (WING & BOOT MIRROF ACCEPTABLE FOR AGE AND MILEAGE

Valuation & Inspection Officer

AA KENYA P.O. Box 40087 - 00100. NAIROBI

Date : 14/10/2025

22. SEATS

C (Center):	ACCEPTABLE FOR AGE AND MILEAGE
F (WING & BOOT MIRROR	ACCEPTABLE FOR AGE AND MILEAGE
R (WING & BOOT MIRROF	ACCEPTABLE FOR AGE AND MILEAGE

23. BODY KIT AND PARKING SENSORS

F (WING & BOOT MIRROR	ACCEPTABLE FOR AGE AND MILEAGE
R (WING & BOOT MIRROF	ACCEPTABLE FOR AGE AND MILEAGE

24. UPHOLSTERY

ACCEPTABLE FOR AGE AND MILEAGE

25. AIR BAGS

ACCEPTABLE FOR AGE AND MILEAGE

26. ROOF LINING

ACCEPTABLE FOR AGE AND MILEAGE

27. UNDERLAY

ACCEPTABLE FOR AGE AND MILEAGE

28. FLOOR

ACCEPTABLE FOR AGE AND MILEAGE

29. INTERNAL MIRRORS

ACCEPTABLE FOR AGE AND MILEAGE

30. SUN ROOFS / PANORAMIC ROOF

ACCEPTABLE FOR AGE AND MILEAGE

31. WOOD WORK

L (EXTERNAL MIRRORS):	ACCEPTABLE FOR AGE AND MILEAGE
R (WING & BOOT MIRROF	ACCEPTABLE FOR AGE AND MILEAGE

32. PAINT WORK: LUSTRE

ACCEPTABLE FOR AGE AND MILEAGE

33. PAINT WORK: COLOUR VARIATION

ACCEPTABLE FOR AGE AND MILEAGE

34. PAINT WORK: REPAIR MATCHING

ACCEPTABLE FOR AGE AND MILEAGE

35. IS THERE EVIDENCE OF ACCIDENT DAMAGE?

✗ NO

Valuation & Inspection Officer

AA KENYA P.O. Box 40087 - 00100. NAIROBI

Date : 14/10/2025

36. IS DAMAGE REPAIR WORK SATISFACTORY?

YES

Section Comments:

all good

Valuation & Inspection Officer

AA K.E.
P.O. Box 40087 - 00100. NAIROBI

Date : 14/10/2025

B: WHEELS

Wheel condition and accessories inspection

1. WHEEL TYPE

LF: ALLOY
LR: POKED
RF: POKED
RR: WIRE

2. WHEEL CONDITION

LF (Left Front):	ACCEPTABLE FOR AGE AND MILEAGE
LR (Left Rear):	ACCEPTABLE FOR AGE AND MILEAGE
RF (Right Front):	ACCEPTABLE FOR AGE AND MILEAGE
RR (Right Rear):	ACCEPTABLE FOR AGE AND MILEAGE

3. CONDITION OF BODY KIT / FENDERS AND WHEEL CAPS

LR (Left Rear):	ACCEPTABLE FOR AGE AND MILEAGE
RF (Right Front):	ACCEPTABLE FOR AGE AND MILEAGE
RR (Right Rear):	ACCEPTABLE FOR AGE AND MILEAGE
LF (Left Front):	ACCEPTABLE FOR AGE AND MILEAGE

Section Comments:

good

Valuation & Inspection Officer

AA KENYA P.O. Box 40087 - 00100. NAIROBI

Date : 14/10/2025

C: TYRES

Tyre condition, tread depth and type inspection

1. TYRE TYPE

LF: CROSS_PLY
LR: CROSS_PLY
RF: CROSS_PLY
RR: CROSS_PLY

2. TREAD DEPTH (MM)

LF: 2_TO_4
LR: 1_TO_2
RF: 1_TO_2
RR: 1_TO_2

3. TYRE CONDITION

RF (Right Front):	ACCEPTABLE FOR AGE AND MILEAGE
RR (Right Rear):	ACCEPTABLE FOR AGE AND MILEAGE
LF (Left Front):	ACCEPTABLE FOR AGE AND MILEAGE
LR (Left Rear):	ACCEPTABLE FOR AGE AND MILEAGE

Section Comments:

all good

Valuation & Inspection Officer

AA KENYA P.O. Box 40087 - 00100. NAIROBI

Date : 14/10/2025

D: COOLING SYSTEM

Radiator, hoses, and coolant inspection

1. IS COOLANT LEVEL CORRECT

✓ YES

2. IS COOLANT CONTAMINATED BY RUST/OIL OR SLUDGE

✓ YES

3. VISIBLE CONDITION OF RADIATOR

✓ ACCEPTABLE FOR AGE AND MILEAGE

4. EXPANSION TANK

✓ ACCEPTABLE FOR AGE AND MILEAGE

5. HOSES

✓ ACCEPTABLE FOR AGE AND MILEAGE

6. HEATER HOSES

✓ ACCEPTABLE FOR AGE AND MILEAGE

7. FAN BELTS

✓ ACCEPTABLE FOR AGE AND MILEAGE

8. FAN

✓ ACCEPTABLE FOR AGE AND MILEAGE

9. ARE THERE ANY LEAKS FROM RADIATOR

✗ NO

10. ARE THERE ANY LEAKS FROM HOSE PIPES

✗ NO

11. ARE THERE ANY LEAKS FROM HEATER HOSES

✗ NO

12. ARE THERE ANY LEAKS FROM CYLINDER HEAD GASKET

✗ NO

13. ARE THERE ANY LEAKS FROM GLOW / HEATER PLUGS

✗ NO

14. ARE THERE ANY LEAKS FROM PUMP

✗ NO

Valuation & Inspection Officer

AA KENYA - NAIROBI
P.O. Box 40087 - 00100

Date : 14/10/2025

15. ARE THERE ANY LEAKS FROM SPARK PLUGS

X NO

16. ARE THERE ANY LEAKS FROM THERMOSTAT HOUSING

X NO

Section Comments:

all good

Valuation & Inspection Officer

AA KENYA P.O. Box 40087 - 00100. NAIROBI

Date : 14/10/2025

E: ENGINE

Engine condition and performance inspection

1. HT CABLES

✓ ACCEPTABLE FOR AGE AND MILEAGE

2. LT CABLES

✓ ACCEPTABLE FOR AGE AND MILEAGE

3. TURBO

✓ ACCEPTABLE FOR AGE AND MILEAGE

4. BATTERY CABLES

✓ ACCEPTABLE FOR AGE AND MILEAGE

5. INTER COOLER

✓ ACCEPTABLE FOR AGE AND MILEAGE

6. CONTACT BREAKER

✓ ACCEPTABLE FOR AGE AND MILEAGE

7. SUPER CHARGER

✓ ACCEPTABLE FOR AGE AND MILEAGE

8. DISTRIBUTOR / MODULE / MAGNETO

✓ ACCEPTABLE FOR AGE AND MILEAGE

9. ENGINE MOUNTINGS

F (WING & BOOT MIRROR ✓ ACCEPTABLE FOR AGE AND MILEAGE
L (EXTERNAL MIRRORS): ✓ ACCEPTABLE FOR AGE AND MILEAGE
R (WING & BOOT MIRROF ✓ ACCEPTABLE FOR AGE AND MILEAGE

10. DRIVING BELTS

✓ ACCEPTABLE FOR AGE AND MILEAGE

11. OIL LEVEL AND CONDITION

✓ ACCEPTABLE FOR AGE AND MILEAGE

12. IS THERE EVIDENCE OF WATER CONTAMINATION?

✗ NO

13. DOES OIL PRESSURE WARNING LIGHT OPERATE CORRECTLY?

✓ YES

Valuation & Inspection Officer

AA KENYA - NAIROBI
P.O. Box 40087 - 00100

Date : 14/10/2025

14. OIL PRESSURE GAUGE READING

3457

15. IS THERE EVIDENCE OF EXCESSIVE LEAKS?

✗ NO

16. IS THERE EVIDENCE OF EXCESSIVE OIL FUMES

✗ NO

17. NOISE LEVEL IN VALVE OPERATING MECHANISM

✓ ACCEPTABLE FOR AGE AND MILEAGE

18. NOISE LEVEL IN BEARINGS

✓ ACCEPTABLE FOR AGE AND MILEAGE

19. NOISE LEVEL IN PISTON / SMALL END ASSEMBLY

✓ ACCEPTABLE FOR AGE AND MILEAGE

20. DOES EXHAUST EMISSION INDICATE RICH MIXTURE

✗ NO

21. DOES EXHAUST EMISSION INDICATE ABNORMAL OIL CONSUMPTION

✗ NO

22. CYLINDER POWER VARIATION

67

Section Comments:

all good

Valuation & Inspection Officer

AA KENYA P.O. Box 40087 - 00100. NAIROBI

Date : 14/10/2025

F: ELECTRICAL EQUIPMENT

Electrical systems and lighting inspection

1. BATTERY

ACCEPTABLE FOR AGE AND MILEAGE

2. BATTERY MOUNTING

ACCEPTABLE FOR AGE AND MILEAGE

3. WIRING

ACCEPTABLE FOR AGE AND MILEAGE

4. HEADLIGHTS

Not inspected

5. PARKING LIGHTS

Not inspected

6. REAR LIGHTS

Not inspected

7. TURN INDICATORS

Not inspected

8. ECU UNIT / ECM UNIT

ACCEPTABLE FOR AGE AND MILEAGE

9. SPOT LIGHTS / ROOF LIGHTS

Not inspected

10. REVERSING LIGHTS

Not inspected

11. NUMBER PLATE LIGHTS

Not inspected

12. COURTESY LIGHTS

ACCEPTABLE FOR AGE AND MILEAGE

13. STARTER

ACCEPTABLE FOR AGE AND MILEAGE

14. DYNAMO / ALTERNATOR

ACCEPTABLE FOR AGE AND MILEAGE

15. HORN(S)

ACCEPTABLE FOR AGE AND MILEAGE

Valuation & Inspection Officer

AA KENYA P.O. Box 40087 - 00100. NAIROBI

Date : 14/10/2025

16. IGNITION WARNING LIGHT

ACCEPTABLE FOR AGE AND MILEAGE

17. MAIN BEAM WARNING LIGHT

ACCEPTABLE FOR AGE AND MILEAGE

18. PANEL LIGHTS

ACCEPTABLE FOR AGE AND MILEAGE

19. LEVEL OF ELECTROLYTE CORRECT?

YES

Section Comments:

all good

Valuation & Inspection Officer

AA KENYA P.O. Box 40087 - 00100. NAIROBI

Date : 14/10/2025

G: FUEL SYSTEM

Fuel delivery and storage system inspection

1. CARBURETOR(S)

✓ ACCEPTABLE FOR AGE AND MILEAGE

2. INJECTION SYSTEM OR HYBRID SYSTEM

✓ ACCEPTABLE FOR AGE AND MILEAGE

3. INJECTOR PUMP

✓ ACCEPTABLE FOR AGE AND MILEAGE

4. FUEL PUMP

✓ ACCEPTABLE FOR AGE AND MILEAGE

5. CONTROLS

✓ ACCEPTABLE FOR AGE AND MILEAGE

6. ACCELERATOR PEDAL & LINKAGE

✓ ACCEPTABLE FOR AGE AND MILEAGE

7. FUEL TANK

✓ ACCEPTABLE FOR AGE AND MILEAGE

8. FUEL PIPES

✓ ACCEPTABLE FOR AGE AND MILEAGE

9. FLEXIBLE HOSES

✓ ACCEPTABLE FOR AGE AND MILEAGE

10. AIR CLEANER

✓ ACCEPTABLE FOR AGE AND MILEAGE

11. IS THERE EVIDENCE OF FUEL LEAKS?

✗ NO

12. IS TUNING NECESSARY?

✗ NO

13. IS IDLING SATISFACTORY?

✓ YES

Valuation & Inspection Officer

AA KENYA P.O. Box 40087 - 00100. NAIROBI

Date : 14/10/2025

Section Comments:

good

Valuation & Inspection Officer

AA OF K
P.O. Box 40087 - 00100, NAIROBI

Date : 14/10/2025

H: FRAME, UNDERSIDE, EXHAUST

Chassis, undercarriage and exhaust inspection

1. IS UNDERSEALING APPLIED?

✗ NO

2. IS CONDITION SATISFACTORY

✓ YES

3. IS THERE EVIDENCE OF CORROSION

✗ NO

4. IS THERE EVIDENCE OF DAMAGE

✗ NO

5. IS THERE EVIDENCE OF REPAIRS

✗ NO

6. CONDITION OF SPRINGS/SUSPENSION MOUNTING

Not inspected

7. DAMPER MOUNTINGS

Not inspected

8. UNDER WINGS

Not inspected

9. BOX SECTIONS

✓ ACCEPTABLE FOR AGE AND MILEAGE

10. CROSS MEMBERS

✓ ACCEPTABLE FOR AGE AND MILEAGE

11. FRONT SUB FRAME

✓ ACCEPTABLE FOR AGE AND MILEAGE

12. REAR SUB FRAME

✓ ACCEPTABLE FOR AGE AND MILEAGE

13. UNDER FLOOR PRESSINGS

✓ ACCEPTABLE FOR AGE AND MILEAGE

14. FRONT EXHAUST PIPES

✓ ACCEPTABLE FOR AGE AND MILEAGE

Valuation & Inspection Officer

AA KE P.O. Box 40087 - 00100. NAIROBI

Date : 14/10/2025

15. MANIFOLD

ACCEPTABLE FOR AGE AND MILEAGE

16. SILENCERS

ACCEPTABLE FOR AGE AND MILEAGE

17. REAR EXHAUST PIPE(S)

ACCEPTABLE FOR AGE AND MILEAGE

18. EXHAUST MOUNTINGS

ACCEPTABLE FOR AGE AND MILEAGE

Section Comments:

good

Valuation & Inspection Officer

AA KENYA P.O. Box 40087 - 00100. NAIROBI

Date : 14/10/2025

I: REAR SUSPENSION

Rear suspension components inspection

1. CONDITION OF SPRINGS

Not inspected

2. DAMPERS

Not inspected

3. BUMP STOPS

Not inspected

4. HYDROLASTIC UNITS

Not inspected

5. HYDROLASTIC PIPES

Not inspected

6. ANTI ROLL BAR

ACCEPTABLE FOR AGE AND MILEAGE

7. ARE HUB BEARINGS NOISY?

Not inspected

Section Comments:

good

Valuation & Inspection Officer

AA OF K P.O. Box 40087 - 00100. NAIROBI

Date : 14/10/2025

J: FRONT SUSPENSION AND STEERING

Front suspension and steering system inspection

1. SPRING

Not inspected

2. DAMPERS

Not inspected

3. BUMP STOPS

Not inspected

4. HYDROLASTIC UNITS

Not inspected

5. HYDROLASTIC PIPES

Not inspected

6. ANTI ROLLER BAR

✓ ACCEPTABLE FOR AGE AND MILEAGE

7. STEERING BOX / RACK

✓ ACCEPTABLE FOR AGE AND MILEAGE

8. STEERING JOINTS

Not inspected

9. POWER STEERING OIL LEAKAGES

✗ NO

10. RODS, BALL JOINTS AND ARMS

Not inspected

11. RUBBER BOOTS

✓ ACCEPTABLE FOR AGE AND MILEAGE

12. PLAY IN STEERING WHEEL

✓ ACCEPTABLE FOR AGE AND MILEAGE

13. WHEEL BEARING

Not inspected

14. SWIVEL PINS & BEARINGS

Not inspected

15. WISH BONE PIVOTS

Not inspected

Valuation & Inspection Officer

AA K... P.O. Box 40087 - 00100. NAIROBI

Date : 14/10/2025

16. ARE WHEEL BEARINGS NOISY?

Not inspected

17. IS A FULL CHECK OF STEERING GEOMETRY NECESSARY?

X NO

Section Comments:

good

Valuation & Inspection Officer

AA Kenya P.O. Box 40087 - 00100. NAIROBI

Date : 14/10/2025

K: GEAR BOX

Transmission system inspection

1. IS GEAR BOX AUTOMATIC?

✓ YES

2. IS FLUID LEVEL CORRECT?

✓ YES

3. IS THERE UNDUE NOISE OR VIBRATION?

✗ NO

4. CONDITION OF MOUNTINGS

✓ ACCEPTABLE FOR AGE AND MILEAGE

5. CONDITION OF LINKAGE

✓ ACCEPTABLE FOR AGE AND MILEAGE

6. DO ALL GEAR SELECTORS FUNCTION SATISFACTORILY?

✓ YES

7. DOES OVERDRIVE FUNCTION SATISFACTORILY?

✓ YES

8. DOES INHIBITOR SWITCH FUNCTION SATISFACTORILY?

✓ YES

9. DOES SYNCHROMESH FUNCTION SATISFACTORILY?

✓ YES

10. DO AUTOCHANGES FUNCTION SATISFACTORILY?

✓ YES

11. DOES KICKDOWN FUNCTION SATISFACTORILY?

✓ YES

12. TRANSFER BOX

✓ ACCEPTABLE FOR AGE AND MILEAGE

13. DO ANY GEARS DISENGAGE UNDER LOAD?

no

14. IS THERE EVIDENCE OF EXCESSIVE OIL LEAKS?

✗ NO

Valuation & Inspection Officer

AA K.E. P.O. Box 40087 - 00100. NAIROBI

Date : 14/10/2025

Section Comments:

good

Valuation & Inspection Officer

AA OF K
P.O. Box 40087 - 00100, NAIROBI

Date : 14/10/2025

L: CLUTCH OR TORQUE CONVERTER

Clutch/torque converter inspection

1. CLUTCH (MANUAL)

✅ ACCEPTABLE FOR AGE AND MILEAGE

2. TORQUE CONVERTER (AUTOMATIC)

✅ ACCEPTABLE FOR AGE AND MILEAGE

3. IS THERE EVIDENCE OF EXCESSIVE NOISE?

❌ NO

4. IS THERE EVIDENCE OF CREEP?

❌ NO

5. IS THERE EVIDENCE OF LEAKS?

❌ NO

6. IS THERE EVIDENCE OF SLIP?

❌ NO

7. IS THERE EVIDENCE OF JUDDER?

❌ NO

8. IS THERE EVIDENCE OF SPIN?

❌ NO

9. IS THERE EVIDENCE OF FIERCENESS?

❌ NO

10. IS THE FLUID LEVEL CORRECT?

❌ NO

Section Comments:

good

Valuation & Inspection Officer

AA KENYA P.O. Box 40087 - 00100. NAIROBI

Date : 14/10/2025

M: TRANSMISSION AND FINAL DRIVE

Drive shafts and final drive inspection

1. CONDITION OF PROPELLER SHAFT

Not inspected

2. FRONT DRIVE SHAFTS - INNER

Not inspected

3. FRONT DRIVE SHAFTS - OUTER

Not inspected

4. 4WD WITH REAR DRIVE SHAFTS

Not inspected

5. PROPELLER SHAFT CENTER MOUNTING

✓ ACCEPTABLE FOR AGE AND MILEAGE

6. UNIVERSAL COUPLINGS

Not inspected

7. FRONT CV JOINTS - INNER

Not inspected

8. FRONT CV JOINTS - OUTER

Not inspected

9. 4WD WITH REAR CV JOINTS

Not inspected

10. RUBBER BOOTS - FRONT

Not inspected

11. 4WD WITH REAR RUBBER BOOTS

Not inspected

12. IS THERE EVIDENCE OF EXCESSIVE NOISE?

✗ NO

13. IS THERE EVIDENCE OF EXCESSIVE OIL LEAKS?

✗ NO

14. IS THERE EVIDENCE OF BACKLASH?

✗ NO

Valuation & Inspection Officer

AA K.E. P.O. Box 40087 - 00100. NAIROBI

Date : 14/10/2025

Section Comments:

all good

Valuation & Inspection Officer

AA KENYA
P.O. Box 40087 - 00100, NAIROBI

Date : 14/10/2025

N: BRAKES

Braking system inspection

1. IS FLUID LEVEL CORRECT?

YES

2. CONDITION OF RESERVOIR

ACCEPTABLE FOR AGE AND MILEAGE

3. MASTER CYLINDER

ACCEPTABLE FOR AGE AND MILEAGE

4. ABS MODULE

ACCEPTABLE FOR AGE AND MILEAGE

5. PIPELINES

ACCEPTABLE FOR AGE AND MILEAGE

6. FLEXIBLE HOSES

ACCEPTABLE FOR AGE AND MILEAGE

7. UNIONS

ACCEPTABLE FOR AGE AND MILEAGE

8. FOOT PEDAL AND LINKAGE

ACCEPTABLE FOR AGE AND MILEAGE

9. HAND BRAKE MECHANISM

ACCEPTABLE FOR AGE AND MILEAGE

10. DISCS & DRUMS

Not inspected

11. BRAKE PADS

Not inspected

12. IS THERE ANY INDICATION OF PRESSURE LOSS?

NO

13. FUNCTION OF FOOT BRAKES

ACCEPTABLE FOR AGE AND MILEAGE

14. FUNCTION OF HAND BRAKES

ACCEPTABLE FOR AGE AND MILEAGE

Valuation & Inspection Officer

AA KE P.O. Box 40087 - 00100. NAIROBI

Date : 14/10/2025

15. FUNCTION OF SERVO SYSTEM

ACCEPTABLE FOR AGE AND MILEAGE

16. FUNCTION OF CABLE OR ELECTRIC SYSTEM

ACCEPTABLE FOR AGE AND MILEAGE

17. IS THERE EVIDENCE OF JUDDER?

NO

18. IS THERE EVIDENCE OF SQUEAL?

NO

19. IS THERE EVIDENCE OF PULL TO THE LEFT / RIGHT?

NO

Section Comments:

good

Valuation & Inspection Officer

AA KENYA P.O. Box 40087 - 00100. NAIROBI

Date : 14/10/2025

O: INSTRUMENTS AND ACCESSORIES

Dashboard instruments and accessories inspection

1. WIND SCREEN WIPERS

Not inspected

2. REAR WIPER

ACCEPTABLE FOR AGE AND MILEAGE ACCEPTABLE FOR AGE AND MILEAGE

3. FRONT WINDSCREEN WASHERS

Not inspected

4. REAR WIND SCREEN WASHER

ACCEPTABLE FOR AGE AND MILEAGE

5. DEMISTERS

Not inspected

6. VENTILATION SYSTEMS

ACCEPTABLE FOR AGE AND MILEAGE

7. SPEEDOMETER

ACCEPTABLE FOR AGE AND MILEAGE

8. MILEAGE RECORDER

ACCEPTABLE FOR AGE AND MILEAGE

9. FUEL GAUGE

ACCEPTABLE FOR AGE AND MILEAGE

10. HEATER

ACCEPTABLE FOR AGE AND MILEAGE

11. AIR CONDITIONER

ACCEPTABLE FOR AGE AND MILEAGE

12. TEMPERATURE GAUGE

ACCEPTABLE FOR AGE AND MILEAGE

13. SEAT BELTS

ACCEPTABLE FOR AGE AND MILEAGE

14. ARE SEAT BELTS B.S.I APPROVED?

YES

Valuation & Inspection Officer

AA KENYA P.O. Box 40087 - 00100. NAIROBI

Date : 14/10/2025

15. DOES INDICATOR SELF CANCEL?

YES

Section Comments:

good

Valuation & Inspection Officer

AA OF K
P.O. Box 40087 - 00100, NAIROBI

Date : 14/10/2025

Q: ROAD TEST

Vehicle road test evaluation

1. EASE OF STARTING - COLD

GOOD

2. EASE OF STARTING - HOT

GOOD

3. PERFORMANCE

GOOD

4. GENERAL HANDLING

GOOD

Section Comments:

all good

Valuation & Inspection Officer

AA KENYA P.O. Box 40087 - 00100. NAIROBI

Date : 14/10/2025

STRING: STRING

string

Valuation & Inspection Officer

AA OF K
P.O. Box 40087 - 00100. NAIROBI

Date : 14/10/2025